Submit 3 Copies to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 1-89

OIL CONSERVATION DIVISION

Revisied 1-1-	ŧ

District Offic	OIL CONCENTATION DIVION							
	P.O. Box 2088							
DISTRICT	Santa Fe, New Mexico 87504-208	8						
P.O. Box 19	30, Hobbs, NM 88240							
DISTRICT	!	API NO. (assigned by OCD on New Wells)						
P.O. Drawer	Dd, Artesia, NM 88210	30-025-06934						
DISTRICT	<u>II</u>	5. Indicate Type of Lease						
1000 Rio Bri	zos Rd., Aztec, Nm 87410	STATE FEE						
		8. State Oil & Gas Lease No.						
		N/A						
	SUNDRY NOTICES AND REPORTS ON WELLS							
	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PI	LUG B 7. Lesse Name or Unit Agreement Name						
	DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"	W.T. MC GOMAK						
	(FORM C-101) FOR SUCH PROPOSALS.)	Camack						
1. Type of		· · · · · · · · · · · · · · · · · · ·						
OIL	GAS							
WELL	X WELL OTHER							
2. Name of	Operator	8. Well No.						
	CHEVRON U.S.A. INC.	5						
3. Address	•	9. Pool name or Wildcat						
P.O. BO	K 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS	PENROSE-SKELLY						
4. Well Loca		ne and 1980 Feet From The EAST Line						
Unit Letter		ne and 1980 Feet From The LAST Line Line LAST Line Language 37E NMPM LEA County						
Section	32 Township 21S Ra							
	3456 GE							
<i>(((((((((((((((((((((((((((((((((((((</i>	Check Appropriate Box to Indecate Nature of Notice, Report	rt. or Other Data						
• •	•	ENT REPORT OF:						
PERFORM R	MEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK	ALTER CASING						
PULL OR AL		* LJ						
OTHER:	OTHER:							
	e Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent date	s, including						
esticated	date of starting any proposed work) SEE RULE 1103.							
	IT IS PROPOSED TO:							
	SET CIBP AT 3590', SPOT 300' OF CMT. F/3590-3290,PLUG WILL COVER KNIGHT SERIES & PENR							
	SPOT 200' CMT F/2770-2570, PLUG COVERS YATES.							
SHOOT HOLES AT 1365', SET CICR AT 1165' & SQZ W/80 SX. CMT & LEAVE 35' ON TOP OF (
PERF AT 350' PUMP 80 SX. CMT INTO HOLES.								
	SPOT 80' CMT TO SURFACE.							

10# P & A MUD WILL BE PLACED BETWEEN ALL CMT. PLUGS.

CUT OFF WELLHEAD AND INSTALL P & A MARKER.

CHANGE WELL STATUS TO P & A.

Č	. 10 WN PLUGGR				este de la companya del companya de la companya de la companya del companya de la companya del companya de la companya de la companya de la companya de la companya del companya de la companya del companya de la companya de la companya de la companya de la companya del companya de la companya de la companya de la company		
hereby certify t	that the informa	ntion above is true and complete Ma44Neur	te to the best o	of my knowledge and belief. TECH. ASSISTANT	DATE:	5-8-92	
YPE OR PRINT	NAME	P.R. MATTHEWS			TELEPHONE N	o (915)687-7812	
APPROVED BY					DATE	MAY 11'92	
CONDITIONS	F APPROVAL.	F ANY:	. ———				