

SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

U-102 (Rev. 1-1-65)  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Gulf Oil Corporation		8. Farm or Lease Name W. T. McComack Btry #2
3. Address of Operator Box 670, Hobbs, New Mexico 88240		9. Well No. 10
4. Location of Well UNIT LETTER <u>H</u> <u>2086</u> FEET FROM THE <u>North</u> LINE AND <u>554</u> FEET FROM THE <u>East</u> LINE, SECTION <u>32</u> TOWNSHIP <u>21-S</u> RANGE <u>37-E</u> N.M.P.M.		10. Field and Pool, or Wildcat Blinebry Gas
15. Elevation (Show whether DF, RT, GR, etc.) 3460' GL		12. County Lea

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/> Abandon Blinebry Gas Zone

### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6605' TD.

Release tubing from Model D packer at 6475' and pull tubing. Squeeze Blinebry Gas perforations 5500' to 5655' with low fluid loss Class C cement. WOC 36 hours. Run 6-1/4" bit and clean out to below lower Blinebry perforations at 5655'. Test Squeezed perforations with 500#, 30 minutes.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ray Stone TITLE Senior Petroleum Engineer DATE February 16, 1973

APPROVED BY Joe D. Ramey TITLE Dist. 1, Supv. DATE FEB 19 1973  
CONDITIONS OF APPROVAL, IF ANY: