

**ATTACHMENT TO C-105
COLLINS & WARE, INC.
J. G. HARE #6**

- | | | |
|-----|---|--|
| 26. | 8110' - 8160' (200 holes)
7915' - 7931' (60 shots)
7780' - 7830' (198 shots)
7738' - 7752' (56 shots, 4 SPF)
7008' - 7204' (116 shots)
4162' - 4190'
5164' - 5298' (69 holes)
7257' - 7267' (22 holes)
5491' - 5921' (76 holes) | PB 7/47
PB 7/47

CIBP @ 7315' 7/61
BP @ 6900' 7/66
Squeezed 4/73
Squeezed 9/77
CIBP @ 7168' 12/92 |
| | | |
| 27. | 8110' - 8160'
8110' - 8160'

7780' - 7830'

7008' - 7204'

4162' - 4190'

5164' - 5298'
5164' - 5298'

5430' - 5930'

5491' - 5921'
5491' - 5921' | 500 gals Western mud acid.
AT w/2000 gals Western Low Tension 20% acid.
Plugback from 7960' to 7900' with 20 sx cement.
Plugback to 7898' with 58 sx cement.

500 gals Western mud acid.
CIBP at 7315' with 1 sx cement plug.
AT w/1000 gals Reg. 15% acid.
Set BP @ 6900' with 1 sx cement plug.
Squeeze 4695' - 4710' w/100 sx + 150 sx cement.
AT w/1000 gals 15% NEFE acid.
Squeezed 4162' - 4190' w/200 sx cement.
AT w/1400 gals 15% NE acid.
FT w/21,000 gals gelled water + 39,000# 20/40 sand.
Squeezed 5164' - 5242' w/150 sx C + 100 sx C.
Squeezed 5263' - 5298' w/ 100 sx cement.
Squeezed 7008' - 7204' w/1350 sx cement.
Set CIBP @ 7168' w/50 sx H cement.

500 gals 15% HCL.
Squeeze 5205' - 5076' w/ 3 bbls cement.
AT w/4000 gals 15% HCL w/ 150 1.3 SG ball sealers.
FT w/65,000 gals 25#, X-linked gel and 175,000# sand. |