P. O. Box 19 Hobbs, NM	1 88241-1980 Energy Jinerals and Natural Resources partment	Form C-140 Originated 11/1/95
811 S. First Artesia, NM	ItOff Conservation Division4 882102040 South Pacheco StreetI - (505) 334-6178Santa Fe, New Mexico 87505Grazos Road(505) 827-7131	Submit Original Plus 2 Copies to appropriate District Office
	APPLICATION FOR QUALIFICATION OF WELL WORKOVER PROJECT AND CERTIFICATION OF APPROVAL	
	EE COPIES OFTHIS APPLICATION AND ALL ATTACHMENTS MUST BE FILED WITH THE APPROPRIAT CE OF THE OIL CONSERVATION DIVISION.	E DISTRICT
I.	Operator: Collins & Ware, Inc OGRID #:O04874	
	Address:508 W. Wall, Suite 1200, Midland, Texas 79701	
	Contact Party: Chuck Sledge Phone: (915) 687-3435	
11.	Name of Well:       Hare, J.G.       No. 7       API #:       30-025-06967         Location of Well:       Unit Letter       M       660       Feet from the       South       line and       990       feet from the         Section       33       Township       21S       Range       37E       NMPM,       Lea       County	West line,
111.	Date Workover Procedures Commenced:       11/18/96         Date Workover Procedures were Completed:       12/07/96	
IV.	Attach a description of the Workover Procedures undertaken to increase the projection from the Well	l.
V.	Attach an estimate of the production rate of the Well (a production decline curve or other acceptable table showing monthly oil and/or gas Project Production) based on at least tweive (12) months of establish which shows the future rate of production based on well performance prior to performing Workover.	method, and ed production
VI.	Pool(s) on which Production Projection is based:	
	06660 Blinebry Oil & Gas	
VII.	AFFIDAVIT:	
	State ofTexas)	
	) ss. County of <u>Midland</u> )	
	Chuck Sledge, being first duly sworn, upon oath states:	
	1. I am the Operator or authorized representative of the Operator of the above referenced Well.	
	2. I have made, or caused to be made, a diligent search of the production records which an available and contain information relevant to the production history of this Well.	e reasonably
	3. To the best of rny knowledge, the data used to prepare the Production Projection for this We and accurate and this projection was prepared using sound petroleum engineering principles	Il is complete
** **	March SU	
1 12 11	(Name) Chuck Sledge	
.4	Operations Engineer (Title)	

.

•.¯

SUBSCRIBED AND SWORN TO before me this 19th day of December, 1996.

	Helly U. Winchuste
My Commission expires:	Notary Public
FOR OIL CONSERVATION DIVISION USE ONLY:	PTE OF TEXAS
VIII. CERTIFICATION OF APPROVAL:	77-25-2000 mm

This Application for Qualification of Well Workover Project is hereby approved and the above referenced Well is designated as a Well Workover Project pursuant to the "Natural Gas and Crude Oil Production Incentive Act" (Laws 1995, Chapter 15, Sections 1 through 8). The Oil Conservation Division hereby verifies the Production Projection for the Well Workover Project attached to this application. By copy of this Application and Certification of Approval, the Division notifies the Secretary of the Taxation and Revenue Department of this Approval and certifies that this Well Workover Project has been completed as of (2m7-916, 19).

and District Supervisor, District Geok **Oil Conservation Division** 

21

2

Date:

IX. DATE OF NOTIFICATION TO THE SECRETARY OF THE TAXATION AND REVENUE DEPARTMENT.

DATE: \_\_\_\_\_

District Office	rnery and a			Revi	
DISTRICT 1 P.O. Box 1980, Hobbs, NM \$\$240		ERVATION		WELL API NO.	
_		Pacheco St.		30-025-06967	
DISTRICT II P.O. Drawer DD, Artesia, NM 8821	o Sant	a Fe, NM	87505	S. Indicate Type of Loase	
DISTRICT III				STATE	FEE
1000 Rio Brazos Rd., Aztoc, NM 87	7410			6. State Oil & Gas Lease No.	
( DO NOT USE THIS FORM FO	NOTICES AND REPOR	OR TO DEEPEN OR	PLUG BACK TO A	7. Lesse Name or Unit Agreement N	
(FO	LESERVOIR. USE "APPLIC. RM C-101) FOR SUCH PRO		T"		Laine
I. Type of Well: OL CAS WELL X WELL	. []	HEX.		Hare, JG	
2. Name of Operator	ollins & Ware, Ir			8. Well No. 7	
. Address of Operator	occinis di Mare, Il	····			
508 W. Wall, Suit	e 1200, Midland,	Texas 79701	 	9. Pool same or Wildcat Blinebry Oil & Gas	
	660 Freet From The S	outh	Linc and 990	Foot From The West	
Section 33	Township 21S		376		Line
	Townsup	Range (Show whether DF, I		NMPM Lea	County
		3461	1 DF		
1. Che	ck Appropriate Box t	o Indicate Nati	tre of Notice, Re	port, or Other Data	
NOTICE OF	INTENTION TO:	1	SUB	SEQUEINT REPORT OF	
	PLUG AND ABAY		MEDIAL WORK		NG [
r-	PLUG AND ABAY		MEDIAL WORK		
RFORM REMEDIAL WORK	 ר		MEDIAL WORK		
ERFORM REMEDIAL WORK	 ר		MEDIAL WORK MMENCE DRILLING SING TEST AND CEI	OPNS. PLUG AND ABAI	
RFORM REMEDIAL WORK	 ר		MEDIAL WORK	OPNS. PLUG AND ABAI	
RFORM REMEDIAL WORK	CHANGE PLANS	см тот	MEDIAL WORK MMENCE DRILLING SING TEST AND CEI HER: add pay	OPNS. PLUG AND ABAI	
ERFORM REMEDIAL WORK MPORARILY ABANDON ULL OR ALTER CASING HER: 2. Describe Proposed or Completed	CHANGE PLANS	timent details, and give lean out fil g PBTD at 60	MEDIAL WORK MMENCE DRILLING SING TEST AND CEI HER: add pay persiment dates, include to 5917 <sup>1</sup> .	OPNS. PLUG AND ABAN MENT JOB.	NDONMENT
ERFORM REMEDIAL WORK [ MPORARILY ABANDON [ MLL OR ALTER CASING [ HER:	CHANGE PLANS	inent details, and give lean out fil g PBTD at 60 n top.	MEDIAL WORK MMENCE DRILLING SING TEST AND CEI HER: add pay persinent dates, include l to 5917 <sup>1</sup> . 08 <sup>1</sup> . Log 595	OPNS. PLUG AND ABAN MENT JOB. to Blinebry ing estimated date of starting any propose Drill cement 5917' -	NDONMENT
ERFORM REMEDIAL WORK [ MPORARILY ABANDON [ JUL OR ALTER CASING [ HER:	CHANGE PLANS	<i>Linemi details, and give</i> <i>Linemi details, and give</i> <i>Linemi details, and give</i> <i>Lean out fil</i> <i>g PBTD at 60</i> <i>n top.</i> 5914' (60 pe 15% Ferchek	MEDIAL WORK MMENCE DRILLING SING TEST AND CEN HER: add pay persiment dates, include l to 5917 <sup>1</sup> . 08 <sup>1</sup> . Log 595 nfs). Set pa acid.	OPNS. PLUG AND ABAN MENT JOB	NDONMENT
ERFORM REMEDIAL WORK [ MPORARILY ABANDON [ JUL OR ALTER CASING [ HER:	CHANGE PLANS	incent details, and give lean out fil g PBTD at 60 n top. 5914' (60 pe 15% Ferchek ac well with	MEDIAL WORK MMENCE DRILLING SING TEST AND CEN HER: add pay persiment dates, include l to 5917 <sup>1</sup> . 08 <sup>1</sup> . Log 595 nfs). Set pa acid.	OPNS. PLUG AND ABAN MENT JOE	NDONMENT [ X #d 5935'. at dize
ERFORM REMEDIAL WORK [ IMPORARILY ABANDON [ JUL OR ALTER CASING [ HER:	CHANGE PLANS	incent details, and give lean out fil g PBTD at 60 n top. 5914' (60 pe 15% Ferchek ac well with Swab well.	MEDIAL WORK MMENCE DRILLING SING TEST AND CEI HER: add pay pertiment dates, include l to 5917 <sup>1</sup> . 08 <sup>1</sup> . Log 595 rfs). Set pa acid. 98,000 gals	OPNS. PLUG AND ABAN MENT JOE	NDONMENT
ERFORM REMEDIAL WORK [ IMPORARILY ABANDON [ JUL OR ALTER CASING [ HER:	CHANGE PLANS	Lean out fil g PBTD at 60 n top. 5914' (60 pe 15% Ferchek ac well with Swab well. x 16' RHBC ;	MEDIAL WORK MMENCE DRILLING SING TEST AND CEI HER: add pay pertiment dates, include l to 5917 <sup>1</sup> . 08 <sup>1</sup> . Log 595 rfs). Set pa acid. 98,000 gals	OPNS. PLUG AND ABAN MENT JOE. to Blinebry ing estimated date of starting any propose Drill cement 5917! – O' – 5500'. Set CIBP cker at 5751' and acid of Delta-Frac 25 carry	NDONMENT [ X #d 5935'. at dize
<pre>ERFORM REMEDIAL WORK [ IMPORARILY ABANDON [ IM</pre>	CHANGE PLANS	imeni details, and give timeni details, and give lean out fil g PBTD at 60 n top. 5914' (60 pe 15% Ferchek ac well with Swab well. x 16' RHBC g	MEDIAL WORK MMENCE DRILLING SING TEST AND CEN HER: add pay <i>periment dates, include</i> l to 5917 <sup>1</sup> . 08 <sup>1</sup> . Log 595 rfs). Set pa acid. 98,000 gals	OPNS. PLUG AND ABAN MENT JOE. to Blinebry ing estimated date of starting any propose Drill cement 5917! – O' – 5500'. Set CIBP cker at 5751' and acid of Delta-Frac 25 carry	NDONMENT
ERFORM REMEDIAL WORK [ IMPORARILY ABANDON [ JUL OR ALTER CASING [ HER:	CHANGE PLANS	imeni details, and give timeni details, and give lean out fil g PBTD at 60 n top. 5914' (60 pe 15% Ferchek ac well with Swab well. x 16' RHBC g	MEDIAL WORK MMENCE DRILLING SING TEST AND CEN HER: add pay <i>periment dates, include</i> l to 5917 <sup>1</sup> . 08 <sup>1</sup> . Log 595 rfs). Set pa acid. 98,000 gals	OPNS. PLUG AND ABAN MENT JOE. to Blinebry ing estimated date of starting any propose Drill cement 5917' - O' - 5500'. Set CIBP cker at 5751' and acid of Delta-Frac 25 carry well on production. <u>Dervisor</u> <u>DATE</u> 12/1	NDONMENT ( xd 5935'. at dize ying 16/96
CREFORM REMEDIAL WORK  CMPORARILY ABANDON  CM	CHANGE PLANS	inent details, and give lean out fil g PBTD at 60 n top. 5914' (60 pe 15% Ferchek ac well with Swab well. x 16' RHBC g	MEDIAL WORK MMENCE DRILLING SING TEST AND CEN HER: add pay <i>periment dates, include</i> l to 5917 <sup>1</sup> . 08 <sup>1</sup> . Log 595 rfs). Set pa acid. 98,000 gals	OPNS. PLUG AND ABAN MENT JOE. to Blinebry ing estimated date of starting any propose Drill cement 5917' - O' - 5500'. Set CIBP cker at 5751' and acid of Delta-Frac 25 carry well on production. <u>Dervisor</u> <u>DATE</u> 12/1	NDONMENT (
CREORM REMEDIAL WORK  CMPORARILY ABANDON  CMPORARILY  CMPORARILY ABANDON  CMPORARILY	CHANGE PLANS	inent details, and give lean out fil g PBTD at 60 n top. 5914' (60 pe 15% Ferchek ac well with Swab well. x 16' RHBC g	MEDIAL WORK MMENCE DRILLING SING TEST AND CEN HER: add pay <i>periment dates, include</i> l to 5917 <sup>1</sup> . 08 <sup>1</sup> . Log 595 rfs). Set pa acid. 98,000 gals	OPNS. PLUG AND ABAN MENT JOE. to Blinebry ing estimated date of starting any propose Drill cement 5917' - O' - 5500'. Set CIBP cker at 5751' and acid of Delta-Frac 25 carry well on production. Dervisor DATE 12/1 TELEPHONE NO. (	NDONMENT

## PRODUCTION DATA REPORT General Header Information

County/Parish Name County/Parish Code Additional Counties Field Name Field Code Lease Name	: 25	State Code Region Code District Code ( ),	:	30 NM 21 )
Operator Name	COLLINS & WARE INCORE 97826	ORATED Enhanced Recovery	:	
Township	23 021S 037E	Well Serial Well Number		02506967066 7
Spot Location Primary Product Formation AAPG Basin Code	33 M OIL 452BLBR 430 BLINEBRY	Mode Field Gravity Coalbed Flag Production Started Production Ended Reservoir Code	::	A 0.0 09/1975 03/1996 414

HARE J. G. NO.7 - J G HARE 7 COLLINS & WARE INCORPORATED

1985 Reported Oil Production = 38496 Bbls Reported Gas Production = 375590 Mcf Reported Water Production = 16234 Bbls



Water	Gas	0:1	Calcul	
- - -	+ + +		ated	

HARE, J. G. NO.7 Production Rate vs Time BBI/Mo or Mcf/Mo vs Months COLLINS & WARE, INC. 06660 BLINEBRY OIL & GAS

Production Dil Gas Water

## PRODUCTION DATA REPORT Calculated Monthly Production Totals J G HARE

LiquidGasWaterMonth(Bbls)(Mcf)(Bbls)	Dec TOTAL	0	0	0
YEAR 1996	Month	Liquid (Bbls)	Gas	Water (Bbls)

HARE J. G. NO.7 - J G HARE 7 COLLINS & WARE INCORPORATED

## PRODUCTION DATA REPORT Forecast Information

		Curve Fit	Projection
Product Type		OIL	
Decline Curve Type		EXPONENTIAL	. – –
Hyperbolic Exponent			_ ~~
Initial Decline (%/Yr)	:	0.000000	
Start Date	:	16.992731	5
End Date	-	01/1992	
Correlation Coefficient	:	09/1996	
Economic Limit (BB1/Mo)	•	0.315935	
Initial Prod. Rate (BB1/Mo)		25 55	
Final Prod. Rate (BB1/MO)		23	
Cum. Reported Production (BBls)		38586	
Projected Life (Years)	•	20200	
Projected Production (BBls)	•		
Ultimate Recovery (BBls)	•		
	•		
Product Type	:	GAS	
Decline Curve Type	:	EXPONENTIAL	_ — —
Hyperbolic Exponent	:	0.000000	
Initial Decline (%/Yr)	:	18.879944 %	s <u>-</u> -
Start Date		03/1993	
End Date	:	09/1996	
Correlation Coefficient	:	0.039642	
Economic Limit (Mcf/Mo)		216	
Initial Prod. Rate (Mcf/Mo)		450	
Final Prod. Rate (Mcf/Mo)		216	
Cum. Reported Production (Mcf)	:	379519	
Projected Life (Years)	:		
Projected Production (Mcf)	:		
Ultimate Recovery (Mcf)	:		

HARE J. G. NO.7 - J G HARE 7 COLLINS & WARE INCORPORATED