			Form C-103
DISTRIBUTION			Supersedes Old
NTA FE	NEW MEXICO OIL CO	NSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
LE		·	
5.G.S.			5a. Indicate Type of Lease
ND OFFICE			State Fee XX
ERATOR			5. State Off 6 Gas Leave No.
SUNDRY DO NOT USE THIS FORM FUR POOP	Y NOTICES AND REPORTS O	N WELLS	
USE MAPPLICATIC	24 FOF FERMIT -" (FORM C-101) FOR 5	UCH PROPOSALS.)	7. Unit Agreement Non.e
	OTKER-		Central Drinkard Unit
Gulf Oil Corporation			8. Farm or Lease Name
duress of Operator	<u> </u>		9. Well No.
Box 670, Hobbs, New Mer	xico 88240		144
ocation of Well			10. Field and Pool, or Wildcat
UNIT LETTER <u>H</u> 2(080 FEET FROM THE North	LINE AND 660 FEET FR	Drinkard
THE East	33 21	- 5 27 19	
THE LINE, SECTION	33 TOWNSHIP 21-	-5 RANGE 37-E NMP	~ <i>UIIIIIIIIIIIIIIIIII</i>
MANANANAN AN A	15. Elevation (Show wheth	er DF, RT, GR, etc.)	12. County
		3449' GL	Lea
Check A	ppropriate Box To Indicare	Nature of Notice, Report or C	
NOTICE OF INT		•	T REPORT OF:
	·		·
FORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
PORARILY ABANDON	F	COMMENCE DRILLING OPNS.	PLUG AND ASANDONMENT
OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
	· · ·	OTHER Perforated, ac	idized and
••••••••••••••••••••••••••••••••••••••	· · · · · · · · · · · · · · · · · · ·	completed in Drinkar	d.
Describe Proposed or Completed Oper work) SEE RULE 1103.	rations (Clearly state all pertinent de		ng estimated date of starting any propose
perforations 6570' to 6	ipment and treated new 5590' with 5500 gallons ce 4600#, minimum 2000#	perforations 6523' to 65 of 15% NE acid. Flushe ISIP 400#. after 1 mi	d with 35 harrels of
reating equipment. Ra	an $2-3/8$ " tubing and se	et at 6506!. Ran rods an	nute on vacuum. Pulled d pump and placed well
reating equipment. Ra production.	an 2-3/8" tubing and se	et at 6506'. Ran rods an	nute on vacuum. Pulled d pump and placed well
reating equipment. Ra	an 2-3/8" tubing and se	t at 6506'. Ran rods an	nute on vacuum. Pulled d pump and placed well
reating equipment. Ra	an 2-3/8" tubing and se	et at 6506'. Ran rods an	nute on vacuum. Pulled d pump and placed well
reating equipment. Ra	an 2-3/8" tubing and se	t at 6506'. Ran rods an	nute on vacuum. Pulled d pump and placed well
reating equipment. Ra	an 2-3/8" tubing and s€	t at 6506'. Ran rods an	nute on vacuum. Pulled d pump and placed well
reating equipment. Ra	an 2−3/8" tubing and s€	et at 6506'. Ran rods an	nute on vacuum. Pulled d pump and placed well
reating equipment. Ra	an 2−3/8" tubing and s€	et at 6506'. Ran rods an	nute on vacuum. Pulled d pump and placed well
reating equipment. Ra	an 2-3/8" tubing and s€	t at 6506'. Ran rods an	nute on vacuum. Pulled d pump and placed well
reating equipment. Ra	an 2-3/8" tubing and s€	et at 6506'. Ran rods an	nute on vacuum. Pulled d pump and placed well

CHED DIT	in Stone	TITLE Project Petroleum Engineer 'DATE M	arch 23, 1976
PROVED BY	Land a Quint	TITLE DATE	MAR 2 - 1976
NDITIONS OF A	PPROVAL, IF ANY:		•

17

ONDITIONS OF APPROVAL, IF ANY:

. •