Submit 3 Copies to Appropriate District Office	Energy,	State of New M erals and Natural R	exico lesources Department	v	Form C-103 Revised 1-1-89	
DISTRICT	OIL CONSERVATION DIVISION					
P.O. Bax 1980, Hobbs, NM 8	8240	2040 Pacheco St.		WELL API NO. 30-025-06985		
<u>DISTRICT II</u> P.O. Drawer DD, Ariesia, NM	88210	Santa Fe, 8	37505	5. Indicate Type of		
DISTRICT III 1000 Rio Brazos Rd., Azzec, N	IM 87410			6. State Oil & Gas I		
	DY NOTICES ANI	REPORTS ON WE	115			
I DO NOT USE THIS FOR	M FOR PROPOSALS T ENT RESERVOIR. US	TO DRILL OR TO DEEPER *APPLICATION FOR PE SUCH PROPOSALS.)	N OR PLUG BACK TO A	7. Lease Name or L	Juit Agreement Name	
1. Type of Well:			<u></u>	E. O. CA	RSON	
WELL	WELL X	OTHER				
2. Name of Operator	<u> </u>			8. Well Na 14		
Titan Resourc	es I, Inc.					
3. Address of Operator	s Suite 500	Midland, TX 797	01	9. Pool name or W Blinebry	Oil and Gas	
4. Well Location	is, suite 500,	Fildland, IA 797	01		<u></u>	
	. 731 Eret F	rom The <u>North</u>	Line and 19	09 Feet From	The West Lin	
					En	
Section 33	Town	thip 21-S F	Range 37-E	NMPM	Lea County	
		10. Elevation (Show whethe 3471 GR	er DF, RKB, RT, GR, elc.)		\//////////////////////////////////////	
					<u> </u>	
11.	· · ·	iate Box to Indicate				
NOTICE	E OF INTENTIO	N TO:	SU	BSEQUENT RI	EPORT OF:	
			REMEDIAL WORK	x		
TEMPORARILY ABANDON						
PULL OR ALTER CASING			CASING TEST AND			
				Pár Ti	ζ _ε . Γ	
OTHER:		[]	OTHER:	<u> </u>	<u>,</u>	
12. Describe Proposed or Con work) SEE RULE 1103.			L.			
	Well fraced 1/96. Prep to clean-out sand and put on pump. Note: Old records report packer stuck. Left 10 jts 3-1/2" EUE frac tubing on top of packer and reduced tubing to 2-3/8". MIRU pulling unit. Could not unset packer at 5643 ft. Could not release on-off tool.					
			-	Jould not release		
	Ran free-point. Tubing stuck at 5350 ft.					
	Cut tubing at 5557 ft. Could not pull tubing. Backed off at 5318 ft and pulled 168 jts 2-3/8".					
11/22,23/96	Attempted to fish tubing left in holeno success. RIH with 4-1/2" wash pipe. Washed and milled out 18 ft tubing. Tubing stuck with frac					
11/24/96	RIH with 4-1/2" sand.	wash pipe. Washe	a and milled out 18	π tubing. Tubi	ng stuck with frac	
11/25/96 thru						
12/20/96	Milled and washe	d over 3-1/2" tubin	g. Recover all of tu	bing and on-off	tool.	
	x	<u></u>	·			
] hereby certify that the informa-	tion above is true and comple	te to the best of my knowledge a	nad belicf.			
SKONATURE	n dut		muz Project Ma	anager	DATE	
TYPE OR PRINT NAME ROT	Lechwar	· · · ·	· · · · · · · · · · · · · · · · · · ·		Tellephone NO.	
	ORIGINAL MONES	A: MORY SEX ON				

----- me -

The start

---- DATE -----

m	 1~	State	1100

(This space for State Use)

APPROVED BY -----

BISTRIA : BERGERSON

E. O. Carson No. 14 C-103 Page 2

- 12/21/96 Washed sand off of packer. RIH with on-off tool.
- 12/23/96 Caught and released packer and pulled out of hole. All fish recovered. RIH with bulldog bailer and cleaned out to 5910 ft. PBTD.
- 12/24/96 RIH with 185 jts 2-3/8" tubing, set at 5896 ft.
- 12/26/96 Swabbed well and cleaned up.
- 12/27/96 RIH with pump and rods and put on production.

JJ/mjl eocar14.103