

E. O. Carson No. 16

C-103

Page 2

12/20-23/96 Milled and fished junk down to packer. RIH with on-off tool. Could not release packer.
12/24/96 RIH overshot and jars. Caught fish. Jars quit.
12/26/96 Tripped tubing, changed jars. Caught fish and jarred packer loose. POOH and LD packer.
All fish recovered. RIH with bulldog bailer and cleaned out to 6510 ft. (Tubb perfs: 5912'-
6119')
12/27/96 RIH with packer and tubing. Swabbed until well cleaned up.
12/31/96 POOH with packer. RIH with tubing for production.
1/2/97 Swabbed well to clean up. Recovered emulsion, iron sulfide, sand and paraffin. Lost swab
mandrel in tubing.
1/3/97 Tripped tubing. Recovered swab mandrel. Ran tubing back in hole. RIH with rods and
pump. Put on production.
1/4/97 thru
1/9/97 Pumping. Recovering load water.
1/10/97 Changed pumping units from 114,000 in-lb unit to 320,000 in-lb unit.
1/10/97 Pulled rods and pump. Changed pump size from 1-1/4" plunger to 1-1/2" plunger.
1/11/97 Put on production.

JJ/mjl

eocar16.103