

SOIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name	
Paddock (San Angelo)	
9. Well No.	
2	
10. Field and Pool, or Wildcat	
Paddock	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	
2. Name of Operator Exxon Corporation Attn: Permits Supervisor	
3. Address of Operator P.O. Box 1600, Midland, TX 79702	
4. Location of Well UNIT LETTER <u>P</u> <u>764</u> FEET FROM THE <u>South</u> LINE AND <u>554</u> FEET FROM THE <u>East</u> LINE, SECTION <u>34</u> TOWNSHIP <u>21S</u> RANGE <u>37E</u> NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Clean out to open hole to 5130'. Perforate 7" casing from 5026' - 5061'. 4 shots/foot. 141 shots total. Acidize open hole with 5000 gal. of 15% HCL. Acidize casing perfs with 8000 gal. of 15% HCL. Put well on pump.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Stephen Johnson</u>	TITLE <u>Administrative Specialist</u>	DATE <u>07-18-88</u>
ORIGINAL SIGNED BY <u>JERRY ECKSTON</u>		
DISTRICT SUPERVISOR		
APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		