

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. <b>3002507011</b>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. <b>004180</b>
7. Lease Name or Unit Agreement Name <b>F F HARDISON B</b>
8. Well No. <b>4</b>
9. Pool name or Wildcat <b>BLINEBRY OIL &amp; GAS</b>

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORMC-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator <b>EXXON CORPORATION</b>
3. Address of Operator <b>ATTN: REGULATORY AFFAIRS ML#14 P. O. BOX 1600 MIDLAND, TX 79702</b>
4. Well Location Unit Letter <b>B</b> : <b>660</b> Feet From The <b>NORTH</b> Line and <b>1980</b> Feet From The <b>EAST</b> Line Section <b>34</b> Township <b>21S</b> Range <b>37E</b> NMPM <b>LEA</b> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>3402 GR</b>

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG & ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: **ABANDON DRINKARD FORMATION** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

04/17/95 RIH W/ CIBP @6400' DUMPED 3.5 SX CMT ON PLUG  
04/18/95 PERF BLINEBRY 5786 TO 5910 1 SPF W/ RHSC 3 1/8" GUN  
04/19/95 ACIDIZE W/ 210 GALS 15% HCL , FRAC W/ 66000# 20/40 SAND AND  
18600 GALS FLUID  
04/20/95 SET CIBP @ 5750'  
04/21/95 ACIDIZE BLINEBRY W/ 294 GALS 15% HCL  
04/22/95 ACIDIZE BLINEBRY PERFS (5500-5715) W/ 2000 GALS 15% HCL AND  
FRAC W/ 169000# 20/40 SAND AND 43900 GALS FLUID  
04/25/95 DO CIBP @ 5750'  
04/27/95 RETURN WELL TO PRODUCTION

DRINKARD PERFS 6448-6577 HAVE BEEN ABANDON

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Sharon B. Timlin TITLE Sr. Staff Office Assistant DATE 05/24/95

TYPE OR PRINT NAME Sharon B. Timlin (915) 688-6166 TELEPHONE NO.

(This space for State Use) ORIGINAL SIGNED BY  
GARY WINK  
FIELD REP. II

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

MAY 31 1995

2P Drinkard