

DUPLICATE

(Form C-103)  
(Revised 7/1/52)

NEW MEXICO OIL CONSERVATION COMMISSION  
Santa Fe, New Mexico

NOV 25 1953

MISCELLANEOUS REPORTS ON WELLS

OIL CONSERVATION COMMISSION

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL		REPORT ON RECOMPLETION OPERATION		REPORT ON (Other)	
				Dually complete	X

November 24, 1953  
(Date)

Hobbs, New Mexico  
(Place)

Following is a report on the work done and the results obtained under the heading noted above at the

Cities Service Oil Company  
(Company or Operator)

Owen  
(Lease)

J. P. "Bum" Gibbins, Inc.  
(Contractor)

Well No. 3 in the NW 1/4 SE 1/4 of Sec. 35

T. 21S, R. 37E, NMPM, Drinkard Pool, Lea County.

The Dates of this work were as follows: 11-13-53 to 11-22-53

Notice of intention to do the work (was) ~~(was not)~~ submitted on Form C-102 on 10-26, 1953,  
(Cross out incorrect words)  
and approval of the proposed plan (was) ~~(was not)~~ obtained.

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

This well was killed with oil and a Baker Model D-5 packer set at 6352'. The hole was filled with mud and the Blinbry was perforated 5530-5565, 5580-5610, 5670-5690 with 2 jets per foot. The tubing was then run and the mud displaced with oil and the perforations acidized with 5000 gallons of 15% acid. The tubing and casing annulus was swabbed dry, but the Blinbry failed to produce oil, gas or water. The well was then filled with mud and the Blinbry perforated 5480-5522. The tubing was run and the mud displaced with oil and all of the perforations were acidized with 6000 gallons. The tubing and casing annulus was then swabbed dry but the Blinbry failed to produce oil, water or gas. It is concluded this zone is non-productive of oil, gas or water and will be abandoned.

Witnessed by C. M. Hartwell  
(Name) Cities Service Oil Company District Superintendent  
(Company) (Title)

Approved: OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name: Charles M. Hartwell

Position: District Superintendent

Representing: Cities Service Oil Company

Address: Box 97, Hobbs, New Mexico

Engineer District 1

NOV 27 1953

(Title)

(Date)