

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.

LC 032096A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

LOCKHART A-35 NO 1

9. API Well No.

30-025-07030

10. Field and Pool, or Exploratory Area

BLINEBRY OIL & GAS

11. County or Parish, State

LEA, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other ADDL BLINEBRY PERFS
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Perforation Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

8-19-92 MIRU. POOH W/ RODS, PUMP & TBG. RIH W/ SCRAPER TO 6450', POOH.
8-20-92 GIH W/ CIBP SET @ 6400', DUMP 2 SX CMT ON TOP OF CIBP.
RIH & PERF BLINEBRY W/ 2 JSPF @ 5845-47, 5856-58, 5860-64, 5872-76, 5890-94, 5898-5402.
5410-12, 5414-18, 5445-46, 5474-75, 5495-95, 6004-12.
RIH W/ RBP SET @ 6144' AND PACKER SET @ 5744'. ACID W/ 1680 gal 15% NEFE HCL ACID W/ 60
BALL SEALERS - AVG PRESS 1800 PSI, AVG RATE 3 BPM.
FRAC W/ 901 BBLs FLUID & 79000# 16/30 OTTOWA SAND @ AVG RATE 35 BPM, AVG PERSS 4800# RD.
RIH W/ 6" BIT & DRILL COLLARS TAG SAND @ 5456' DRILL TO 5487' FELL THROUGH CLEAN OUT SAND
TO TOP OF RBP. CIRC HOLE CLEAN, POOH. GIH LATCH ONTO RBP POOH.
GIH W/ PRODUCTION EQUIP, SET SN AT 6031'.
RDMO.

WELL RETURNED TO PRODUCTION ON 9-2-92

14. I hereby certify that the foregoing is true and correct

Signed [Signature] Title SR. REGULATORY SPEC Date 9-3-92

(This space for Federal or State office use)

Approved by _____ Title _____ Date _____
Conditions of approval, if any:

RECEIVED
JAN 13 1992
ORD NOSES OFFICE