

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

COPY TO
SUBMIT IN (Other instr n: re-verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. LC 032096 a	
2. NAME OF OPERATOR Continental Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR Box 460 - Hobbs, New Mexico		7. UNIT AGREEMENT NAME NMFU	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 1980' FWL, Sec 35-21S-37E, Lea County, New Mexico		8. FARM OR LEASE NAME Lockhart A-35	
14. PERMIT NO.		9. WELL NO. 3	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3388 DF		10. FIRM AND POOL, OR WILDCAT Drinkard Tubbs Blinbry	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 35-21S-37E	
		12. COUNTY OR PARISH Lea	
		13. STATE New Mexico	

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

Squeeze & Perforate

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Set DM tool at 6375. Squeezed Drinkard perms 6396-6548 w/150 sx. Reversed out 10 sx. Drilled out DM tool & cement from 6375-6495. Perforated Drinkard at 6397, 6400, 6405, 6421, 6426, 6449, 6444, 6460, 6464, & 6482 w/1 JSPF. Acidized w/1500 gals. Fraced w/16,000 gals crude, 16,000# sd, & 800# "ADOMITE ADDITIVES". After workover well flowed 103 bbls oil, 2 BW, w/1555.3 MCFGPD, 24/64" choke, GOR 15,100.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE **Assistant District Manager** DATE **3-6-64**

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

DATE

USGS (5) NMOCC (2) ABS PAN AM - HBS (3) ATL-ROSW (2)
CALIF OIL Houston & Midland (1 ea)

*See Instructions on Reverse Side

J. L. GORDON

ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.