

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REDEEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input type="checkbox"/>
1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		5. State Oil & Gas Lease No.
2. Name of Operator MORANCO		7. Unit Agreement Name
3. Address of Operator P. O. Box 1860, Hobbs, NM 88240		8. Farm or Lease Name E. M. Elliott
4. Location of Well UNIT LETTER E 1980 FEET FROM THE North LINE AND 560 FEET FROM West LINE, SECTION 35 TOWNSHIP 21S RANGE 37E NMPM.		9. Well No. 11
15. Elevation (Show whether DF, RT, GR, etc.)		10. Field and Pool, or Wildcat Blinebry
12. County Lea		

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER Commingling <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Proposal: Commingling of Blinebry and Drinkard zones April 4, 1979

1. Pull tubing and Brown 2" X 7" BP-4 packer.
2. Remove Model "B" expendable plug from Baker Model "D" packer.
3. Acidize perforations 5634-6459'.
4. Run tubing and place well on production.

(Order No. R-5936)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNED Jerry Sexton Orig. Signed by Jerry Sexton APPROVED BY Dist 1, Supv.	TITLE Agent	DATE April 3, 1979	
CONDITIONS OF APPROVAL, IF ANY:		DATE APR 4 1979	

RECEIVED

APR 8 1979

U.S. COMMISSION ON
THE STATUS OF WOMEN