

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dual (Drinkard Oil-Blinebry Gas)		7. Unit Agreement Name Mark Owen
2. Name of Operator MARATHON OIL COMPANY		8. Farm or Lease Name Mark Owen
3. Address of Operator P.O. Box 2409, Hobbs, New Mexico 88240		9. Well No. 2
4. Location of Well UNIT LETTER M, 660 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 35 TOWNSHIP 21-S RANGE 37-E NMPM.		10. Field and Pool, or Wildcat Drinkard
15. Elevation (Show whether DF, RT, GR, etc.) GL 3374'; KDB 3386'		12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pull 2-3/8" tubing and packer.
2. Run CIBP and set at approximately 6400'; To abandon open hole section 6416'-6553'. Cap BP w/1 sx. cement.
3. Perforate Upper Drinkard porous intervals.
4. Stimulate Drinkard perfs.
5. Test Upper Drinkard. Set RBP at 5600'.
6. Stimulate Blinebry perfs 5436'-5630'.
7. Run in hole with 2-3/8" tubing and 5-1/2" packer. Set packer approximately 100' above Drinkard perfs.
8. Test Blinebry zone.
9. Place well on production, producing Drinkard oil thru tubing and Blinebry gas thru annulus.

Dist.
R.P.S.
J.C.H.
File

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED David D. Strubler

TITLE Engineer Technician

DATE March 5, 1976

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: