NO. OF COPIES RECEIVED]						
DISTRIBUTION	NEW MEXICO OIL CONS	Form C-101					
SANTA FE	-	Revised 1-1-65					
FILE			Í	5A. Indicate	Type of Lease		
U.S.G.S.		FEE X					
LAND OFFICE	.5. State Oil & Gas Lease No.						
OPERATOR	1 ·						
· · · · · · · · · · · · · · · · · · ·							
APPLICATION FOR PERMIT TO DRILL, DEEPEN, OR PLUG BACK							
la. Type of Work				7. Unit Agree	ment Name		
	DEEPEN 🔀	PL UC					
b. Type of Well			8. Farm or Lease Name				
OIL X GAS WELL	OTHER	ZONE MI	ZONE X	Mark Ow	en		
2. Name of Operator				9. Well No.	4		
Marathon Oil Comp	any				7		
3. Address of Operator					10. Field and Pool, or Wildcat		
P. O. Box 2409, Hobbs, New Mexico 88240				Drinkard			
4. Location of Well	K 1980	FEET FROM THE SOL	ith LINE	MMM			
	LOCA120						
AND 1980 FEET FROM THE	West Line of sec. 35	TWP. 21-5 RGE. 37	-Е имрм				
			1.11111	12. County			
ΛΙΙΙΙΙΙΙΙΙΙΙΙΙΙ				Lea			
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			IIIIII			
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	*******	19. Proposed Depth	13A. Formation	a l	20. Rotory or C.T.		
		7435	I	Abo	Rotary		
21. Elevations (Show whether DF, RT, e	tc.) 21A. Kind & Status Plug. Bond	21B. Drilling Contractor	Contractor 22. Approx. Date Work will start		Date Work will start		
3371 GL 3383 DF	Current	Unknown July 17, 1974		, 1974			
23.							
PROPOSED CASING AND CEMENT PROGRAM							

	OORCHIL			*······	
SIZE OF HOLE	SIZE OF CASING	WEIGHT PER FOOT	SETTING DEPTH	SACKS OF CEMENT	EST. TOP
17"	13-3/8"	48#	302'	250	Circ.*
11"	8-5/8"	32#	2794 '	1500	Circ.*
8''	5-1/2"	17#	6452*	500	3700 ' *
	I PROPOSED		Į	1 1	
4-3/4"	3-1/2" Lin	er 9.2#	6427/7435'	75	6427 '

Attempted to add Blinebry completion and dual well in September, 1964. Abandoned Blinebry perfs. 5695-5881' W/500 sx. cement and Blinebry perfs. 5679-5730' W/100 sx. cement. Original completion in Drinkard (open hole: 6452-6535') abandoned in May, 1969 with CIBP @ 5345' with 2 sx. cement cap.

Recompletion in Paddock (5132-5207') was unsuccessful and well is currently shut in. Plan to squeeze to abandon Paddock perfs. 5132-5207' with 125 sx. cement. Drill and clean out to original T.D. Drill to new TD - 7435'. Log well.

Run 3-1/2" from 6427 to 7435' utilizing liner hanger/pkr. with 75 sx. cement. Pressure test liner & liner top. Perf., treat and test Abo zone. Set 5-1/2" packer (with retrievable tubing plug in place) above top Abo perf. Perf., treat and test Drinkard zone. Run down hole equipment to complete well as Drinkard/Abo dual.

*Calculated

IN ABOVE SPACE DESCRIBE PROPOSED PROGRAM: IF PROPOSAL IS TO DEEPEN OR PLUG BACK, GIVE DATA ON PRESENT PRODUCTIVE ZONE AND PROPOSED NEW PRODUC-TIVE ZONE, GIVE BLOWOUT PREVENTER PROGRAM, IF ANY.

I hereby certify that the information above is true and com Signed	plete to the best of my knowledge and belief. 				
(This space for State Use)					
CONDITIONS OF APPROVAL, IF ANY:	FOR 90 DAYS UNLESS DRILLING COMMENCED,				