

NEW MEXICO STATE LAND OFFICE.
SANTA FE, NEW MEXICO

DEPARTMENT OF THE STATE GEOLOGIST
SANTA FE

NOTICE OF INTENTION TO ABANDON WELL

Notice must be given at least five days before work is to begin to the State Geologist or to the proper Oil and Gas Inspector. It is desirable that a representative of the Department of the State Geologist witness the plugging of wells being abandoned whenever possible. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to the sender. Submit this notice in duplicate.

Mr. **P. J. Vesely** **Wink, Texas.** ~~XXXXX~~ **May 17,** 19**35**
Santa Fe, New Mexico.

Dear Sir:

You are hereby notified that it is our intention to abandon **B. W. Arnold** Well
No. **1** in **SE/4** of Sec. **11** of Sec. **2892**, T. **22 28S**, R. **34E**,
N. M. P. M., **Hobbs** Oil Field, **Lea** County.
We plan to commence work on **May 17, 1935**, 19**35**.

The reasons for wishing to abandon the well are as follows:

Dry Hole

The present condition of the well is as follows: **Dry Hole**

The work which we propose to do in abandoning the well is as follows: **Cement back 400 feet from bottom which is 4757', making top of cement 4357'; then fill with heavy mud to 2700', pump in 50 sacks cement, shoot off 10" casing and pull same, then run in drill pipe and cement up to 1000' to cement off water sand, then fill with mud to top; cement marker 4' above ground, leaving in 15 1/2" casing.**

Approved **JUN 13 1935** 19**35**

Except as follows:

Sincerely yours,

Repelle Oil Company

Company or Operator.

By **L. Barrett**

Position **District Superintendent**

Send communications regarding this well to

Name **Above**

Address **Drawer P, Wink, Texas.**

P. J. Vesely
State Geologist or Oil and Gas Inspector.

