

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-07793
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	WARREN MCKEE UNIT
8. Well No.	117
9. Pool name or Wildcat	WARREN MCKEE

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Amerada Hess Corporation	
3. Address of Operator P. O. Drawer D, Monument, NM 88265	
4. Well Location Unit Letter <u>H</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>EAST</u> Line Section <u>18</u> Township <u>20S</u> Range <u>38E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3572' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-13 thru 3-29-96

MIRU Tyler Well Svc. pulling unit. Removed wellhead & installed BOP. Star Tool loaded 5-1/2" csg. w/1 bbl. water & press. up to 500 PSI for 15 min. Held OK. Ran 4-3/4" bit & tagged up on CIBP at 8878'. Drld. fr. 8878' to PBD at 9312'. Circ. clean. Re-ran bit & tagged up at 9250'. Tri-Cone Svc. croke circ. w/air & repeatedly cleaned out sand to PBD. TIH w/5-1/2" x 2-7/8" Baker TAC on 2-7/8" tbg. Set SN OE at 8847' w/TAC at 8748'. Removed BOP & installed wellhead. Ran 20 x 125 RHBM 16-6-S-5 pump on rods. Spaced out pump & checked pump action. RDPU & cleaned location. Changed well status fr. TA'd to pumping.

Test of 4-4-96: Pumped 1 b.o., 114 b.w., & gas TSTM in 24 hours.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE R. L. Wheeler, Jr. TITLE Admin. Svc. Coord. DATE 4-8-96

TYPE OR PRINT NAME R. L. Wheeler, Jr. TELEPHONE NO. 505 393-2144

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: