

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Amerada Hess Corporation	8. Farm or Lease Name Fred Turner, Jr. "A"
3. Address of Operator Box D, Monument, New Mexico 88265	9. Well No. 1
4. Location of Well UNIT LETTER <u>A</u> <u>990</u> FEET FROM THE <u>North</u> LINE AND <u>990</u> FEET FROM THE <u>East</u> LINE, SECTION <u>19</u> TOWNSHIP <u>20S</u> RANGE <u>38E</u> N.M.P.M.	10. Field and Pool, or Wildcat UNDESIGNATED
15. Elevation (Show whether DF, RT, GR, etc.) 3547' GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER Progress report ☒  
ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pump tested open hole section fr. 3708' to 4150' from 1-23-86 to 1-28-86. Pulled rods, pump & tbg. Ran Meridian inflatable pkr. on 2-7/8" tbg. & set pkr. in open hole at 4030' with cast iron shear disc at 4037' & tbg. set, bull plugged at 4068'. Released on-off tool above pkr. & swab tested open hole section fr. 3708' to 4030'. Caught on-off tool, loaded tbg. & broke cast iron shear disc at 4037'. Swab tested open hole section fr. 4030' to 4150'. Had continuous gas blow. Re-set pkr. in open hole at 3917' & attempted to swab test open hole section fr. 3917' to 4150' but pkr. failed to hold. Pulled tbg. & pkr., ran tbg., pump & rods and started pump testing open hole fr. 3708' to 4150'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED E.B. Eiseley TITLE Supv. Adm. Ser. DATE 2-6-86

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT 1 SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

FEB 10 1986