

DEPA
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE
(Other Instructions on Re-
verse side)Form approved,
Bureau No. 42 H1424
5. LEASE DESIGNATION AND SERIAL NO.

LC 031670 (a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" (for proposals.)

JUN 25 10 20 AM '68

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ <i>Water Injection</i>	7. UNIT AGREEMENT NAME <i>NIMFU</i>
2. NAME OF OPERATOR <i>Continental Oil Company</i>	8. FARM OR LEASE NAME <i>SEMI Permian</i>
3. ADDRESS OF OPERATOR <i>Box 460, Hobbs, New Mexico 88240</i>	9. WELL NO. <i>31</i>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <i>660' FNL + 1930' FWL, Section 19, T-20S, R-38E, Lea County, New Mexico.</i>	10. FIELD AND POOL, OR WILDCAT <i>NIMFU</i>
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) <i>3554' RT</i>
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <i>S-19, T-20S, R-38E</i>
	12. COUNTY OR PARISH <i>Lea</i>
	13. STATE <i>NM</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☒(Other) ☐FULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

In order to eliminate communication and squeeze off the Eamont gas zone to prevent water injection into that zone the following procedure is proposed.

Squeeze perfs 3185 to 3504 with 125 sacks low water loss cement with low pressure squeeze.

Drill out cement and test.

Return well to injection.

18. I hereby certify that the foregoing is true and correct

SIGNED

Robert Gault III

TITLE

Adm. Sec. Chief

DATE

6-14-68

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

USGS-5 att-Ros-2 Chas-Mid-2 Par-Amo-Hobbs-2 file

*See Instructions on Reverse Side

JUN 17 1968

A. H. BRUNN
DISTRICT ENGINEER