

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPL
(Other instructions
verse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

6. INDIAN, ALIQUOT, OR TRIBE NAME
LC 031670 (a)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

7. UNIT AGREEMENT NAME

2. NAME OF OPERATOR

NMPU

Continental Oil Company

8. FARM OR LEASE NAME

SEMU Permian

3. ADDRESS OF OPERATOR

9. WELL NO.

P.O. Box 460, Hobbs, N.M.

31

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

10. FIELD AND POOL, OR WILDCAT

At surface

**660' FNL & 1980' FWL of Sec. 19, T-20S,
R-38E**

11. SECTION, T., R., OR W. 1/4, IN
SURVEY OR AREA

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3554' RT

12. COUNTY OF PERMIT 13. STATE

Lea N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

Dual Complete

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

It is proposed to dually complete the subject well in the Seven
Rivers and Upper Queen formations for Eumont gas production, using the
following procedures:

1. Rig up.
2. Pull tubing and packer.
3. Set Bridge Plug.
4. Perf from logs.
5. Acidize if necessary
6. Test gas productive zones
7. Pull bridge plug.
8. Run dual completion equipment and place on production.

We respectfully request your permission to do the above
work. The well is presently a water injection well.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE **Staff Supervisor**

DATE **7-14-66**

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

USGS -2, Atl-Ros 2, Pan Am- Hobbs 3, Calif Mid -2

*See Instructions on Reverse Side

APPROVED
JUL 18 1966
A. R. BROWN
DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.