

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
HOBBS, NEW MEXICO

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER <u>Water Injection</u>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR <u>Conoco Inc</u>	8. FARM OR LEASE NAME <u>Warren McKee</u>
3. ADDRESS OF OPERATOR <u>P.O. Box 460 - Hobbs NM 88240</u>	9. WELL NO. <u>28</u>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <u>1980' FSL & 2310' FEL - Unit Letter J</u>	10. FIELD AND POOL, OR WILDCAT <u>MIRU / Warren McKee</u>
14. PERMIT NO. <u>30-025-07831</u>	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>20-20S-3SE</u>
15. ELEVATIONS (Show whether OF, RT, GR, etc.)	12. COUNTY OR PARISH <u>Lea</u>
	13. STATE <u>NM</u>

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PCILL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) Clean Out & Acidize ☒
REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting, and pertinent to this work.)

Work started on 6/6/87. MIRU. Release Baker 20k-set pks & POOH. Drill out fill from 9070'-9195'. Drill out sand & iron sulfide from 9190'-9170'. Set pks at 8950'. Pressure up backside to 500 psi. Acidize McKee pks (9020'-9135') in 2 equal stages with total 60 gal 15% HCL-NE-FE acid. Rest between stages w/ 120 lb sack salt. Flush w/ 59 bbls FFW. Swab 70 BW. Release pks & POOH. Gain hole with 7" 20k-set pks & 287, ts 2 3/4" Hg. Circ 280 bbls pks fluid. Land pks at 8720'. Flange up wellhead. Rig down. Completed work on 6/14/87

18. I hereby certify that the foregoing is true and correct.

SIGNATURE [Signature] TITLE Administrative Supervisor DATE July 28, 1987

(Leave blank for Federal or State office use)

APPROVALS OF APPROVAL, IF ANY:

TITLE

DATE

*See instructions on Reverse Side

Subject to
Like Approval
by State

This document makes it a crime for any person knowingly and willfully to make to any department or agency of the BLM a false or fraudulent statement or representation as to any matter within its jurisdiction.

RECEIVED
AUG 10 1987
OCD
HOBBS OFFICE