

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name B.M. Marcus
9. Well No. 1
10. Field and Pool, or Wildcat Skaggs Grayburg
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Amerada Hess Corporation	
3. Address of Operator Drawer "D", Monument, New Mexico 88265	
4. Location of Well UNIT LETTER C 660 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 20 TOWNSHIP 20-S RANGE 38-E NMFM.	
15. Elevation (Show whether DF, RT, GR, etc.)	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.


Plan to plug as follows:

1. Spot 100' cement accross perfs. 3906' to 4010' or set cast iron bridge plug in 4-1/2" casing with 35' cement on top bridge plug.
2. Cut 4-1/2" casing. Spot 100' cement in and out bottom 4-1/2" stub.
3. Spot 100' cement plug in 9-5/8" casing opposite top of Salt.
4. Spot 10 sx. cement plug at surface with dry hole marker with 9.3# mud between plugs.

The N.M.O.C.C. will be notified 24 hrs. prior to setting bottom plug.

NOTE: Verbal approval of the above by Mr. Joe D. Ramey 1-22-73.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED 	TITLE Supver., Admin. Services	DATE 1-23-73
APPROVED BY Orig. Signed by Joe D. Ramey Dist. I, Supv.	TITLE	DATE JAN 29 1973
CONDITIONS OF APPROVAL, IF ANY:		