Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR RUPEAU OF LAND MANAGEMENT

FORM APPROVED

Budget Bureau No. 1004-0135

Date

BUREAU OF LAND MANAGEMENT		Expires: March 31, 1993	
		Lease Designation and Serial No. LC-031670B	
SUNDRY NOTICES AND REPORTS ON WELLS		6. If Indian, Allottee or Tribe Name	
o not use this form for proposals to drill or to deep Use "APPLICATION FOR PERMIT -" for s			
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation	
Type of Weil			
X Oil Gas INJECTION			
Well Well Other Name of Operator		8. Well Name and No. SEMU MCKEE	
CONOCO INC.		Well # 11 9. API Well No.	
Address and Telephone No.	,		
10 DESTA DR. STE 100W, MIDLAND, TX. 79705 (915) 686 - 5424 Location of Well (Footage, Sec., T., R., M., or Survey Description) SURFACE: 660' FNL & 660' FWL of Section 29, T-20-S, R-38E, Unit Letter 'D' TD: Same		30-025-07846 10. Field and Pool, or Exploratory Area	
		Warren McKee Simpson 11. County or Parish, State	
		LEA, NM	
		LEA, NIVI	
CHECK APPROPRIATE BOX(s) TO INDIC.	ATE NATURE OF NOTICE, REPORT, OF	R OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION	TION	
Notice of Intent	. Abandonment	Change of Plans	
	Recompletion	New Construction	
X Subsequent Report	Plugging Back	Non-Routine Fracturing	
	Casing Repair	Water Shut-Off	
Final Abandonment Notice	Altering Casing	Conversion to Injection	
	X Other	Dispose Water	
	X Other Acidize & Scale Squeeze	(Note: Report results of multiple completion on Well	
Describe Proposed or Completed Operations (Clearly state all pertine directionally drilled, give subsurface locations and measured and	Acidize & Scale Squeeze Acidize & Scale Squeeze ant details, and give pertinent dates, including estimated date o	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) If starting any proposed work. If well is	
1-24-96 MIRU. Attempted to POH w/ rods. Unable 1-25-96 Parted rods. Stripped out of hole. 1-26-96 Finish stripping out of hole. Found carbon 1-29-96 Establish circ. w/ 9# brine. Pickled tubing 1-30-96 RIH and set pkr at 3440'. Acidize well w/ 2	Acidize & Scale Squeeze ant details, and give pertinent dates, including estimated date o true vertical depths for all markers and zones pertinent to this	(Note: Report results of multiple completion on West Completion or Recompletion Report and Log form.) If starting any proposed work. If well is work.)* If g open-ended. SION. If well is work and tubing. If open @ 350#.	
1-24-96 MIRU. Attempted to POH w/ rods. Unable 1-25-96 Parted rods. Stripped out of hole. 1-26-96 Finish stripping out of hole. Found carbon 1-29-96 Establish circ. w/ 9# brine. Pickled tubing 1-30-96 RIH and set pkr at 3440'. Acidize well w/ 2	Acidize & Scale Squeeze ant details, and give pertinent dates, including estimated date of true vertical depths for all markers and zones pertinent to this to unseat pump. ate scale buildup on inside of tubing. RIH w/ tubin w/ 500 gals. 15% NEFE - HCL. Reversed out. PO 2000 gals. 15% NEFE HCL at 2bpm @ 2500#. Inje	(Note: Report results of multiple completion on West Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* g open-ended. SION. oOH. RIH w/pkr and tubing. ection dropped to 2bpm @ 350#. string.	
1-24-96 MIRU. Attempted to POH w/ rods. Unable 1-25-96 Parted rods. Stripped out of hole. 1-26-96 Finish stripping out of hole. Found carbon 1-29-96 Establish circ. w/ 9# brine. Pickled tubing 1-30-96 RIH and set pkr at 3440'. Acidize well w/ 2	Acidize & Scale Squeeze ant details, and give pertinent dates, including estimated date of true vertical depths for all markers and zones pertinent to this to unseat pump. ate scale buildup on inside of tubing. RIH w/ tubin w/ 500 gals. 15% NEFE - HCL. Reversed out. PO 2000 gals. 15% NEFE HCL at 2bpm @ 2500#. Inje	(Note. Report results of multiple completion on Well Completion or Recompletion Report and Log form.) if starting any proposed work. If well is work.)* g open-ended. SION. IOH. RIH w/pkr and tubing. ection dropped to 2bpm @ 350#.	
directionally drilled, give subsurface locations and measured and 1-24-96 MIRU. Attempted to POH w/ rods. Unable 1-25-96 Parted rods. Stripped out of hole. 1-26-96 Finish stripping out of hole. Found carbon 1-29-96 Establish circ. w/ 9# brine. Pickled tubing 1-30-96 RIH and set pkr at 3440'. Acidize well w/ 2 Scale squeezed w/ inhibitor and flushed w	Acidize & Scale Squeeze ant details, and give pertinent dates, including estimated date of true vertical depths for all markers and zones pertinent to this to unseat pump. ate scale buildup on inside of tubing. RIH w/ tubin w/ 500 gals. 15% NEFE - HCL. Reversed out. PO 2000 gals. 15% NEFE HCL at 2bpm @ 2500#. Inje w/ 260 bbls. 2% KCL. POOH w/ pkr. RIH w/ prod.	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* g open-ended. SION. oOH. RIH w/pkr and tubing. ection dropped to 2bpm @ 350#. string.	
directionally drilled, give subsurface locations and measured and 1-24-96 MIRU. Attempted to POH w/ rods. Unable 1-25-96 Parted rods. Stripped out of hole. 1-26-96 Finish stripping out of hole. Found carbon 1-29-96 Establish circ. w/ 9# brine. Pickled tubing 1-30-96 RIH and set pkr at 3440'. Acidize well w/ 2 Scale squeezed w/ inhibitor and flushed w	Acidize & Scale Squeeze ant details, and give pertinent dates, including estimated date of true vertical depths for all markers and zones pertinent to this to unseat pump. ate scale buildup on inside of tubing. RIH w/ tubin w/ 500 gals. 15% NEFE - HCL. Reversed out. PO 2000 gals. 15% NEFE HCL at 2bpm @ 2500#. Inje w/ 260 bbls. 2% KCL. POOH w/ pkr. RIH w/ prod.	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* g open-ended. SION. oOH. RIH w/pkr and tubing. ection dropped to 2bpm @ 350#. string.	
1-24-96 MIRU. Attempted to POH w/ rods. Unable 1-25-96 Parted rods. Stripped out of hole. 1-26-96 Finish stripping out of hole. Found carbon 1-29-96 Establish circ. w/ 9# brine. Pickled tubing 1-30-96 RIH and set pkr at 3440'. Acidize well w/ 2	Acidize & Scale Squeeze ant details, and give pertinent dates, including estimated date of true vertical depths for all markers and zones pertinent to this to unseat pump. ate scale buildup on inside of tubing. RIH w/ tubin w/ 500 gals. 15% NEFE - HCL. Reversed out. PO 2000 gals. 15% NEFE HCL at 2bpm @ 2500#. Inje w/ 260 bbls. 2% KCL. POOH w/ pkr. RIH w/ prod.	(Note: Report results of multiple completion on West Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* g open-ended. SION. oOH. RIH w/pkr and tubing. ection dropped to 2bpm @ 350#. string.	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Title __

Approved by
Conditions of approval, if any

