N.W.	O.	$\mathbf{o}$	ns.	JIVIS	<b>SIC</b> in a
1625	N.	Pre	nct	ı Dr.	
Uabb		10£	വവ	240	n. 1.

Form 3160-5 June 1990)	DEPARTMEN	TED STATES NT OF THE INT LAND MANAG		Hobbs. MM		Budget Bure	APPROVED  au No. 1004-0135  March 31,1993  on and Serial No.		
Do not	SUNDRY NOTICES use this form for proposals to dr Use "APPLICATION FO	ill or to deepen	or reentry to	a different reserv			031695A se or Tribe Name		
		IN TRIPLICA	TE		7.	If Unit or CA, A	greement Designation		
1. Type of W	Vell  Gas  Well □ Other				8. V	Vell Name and N	No.		
2. Name of (						SEMU	J, Well #16		
Conoc	o, Inc.				9. A	API Well No.			
3. Address at	nd Telephone No.				3	3 <mark>0-025-</mark> 0786	53		
10 De	sta Drive Ste. 100W, Midland, Tx. 7	79705-4500 (915	6) 686- <mark>558</mark> 0/68	4-6381	10.	10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec., T. R. M. or Survey Description)							Eumont Yates Seven Rivers Qn		
10001 THE A 10001 THE							11. County or Parish, State		
1980' FNL & 1980' FWL Sec 30, T20S, R38E						Lea	a, N.M.		
12.	CHECK APPROPRIATE BOX	(s) TO INDICA	TE NATURE	OF NOTICE, RE	PORT,	OR OTHER	R DATA		
	TYPE OF SUBMISSION TYPE OF ACTION								
	Notice of Intent	OR RECORDS	Abandonment		Ļ	Change of Pla	ans		
	2	7	Recompletion		Ļ	New Construc	ction		
	Subsequent Report		Plugging Back		<u> </u>	Non-Routine	Fracturing		
		1 2000   N	Casing Repair		Ļ	☐ Water Shut-○	)ff		
	Final Abandonment Notice	į	Altering Casing	ı	Ĺ	Conversion to	> Injection		
		aca	Other ——		<u> </u>	Dispose Wate	ier of multiple completion on Wei		
•		COLUMN			C	Completion or Recon	npletion Report and Log form.		
13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drill give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*  1-31-00: MIRU, unseated pump, POOH w/rods & pump, removed wellhead & install BOP, rigged up reverse unit, tested to 1000# (held), POOH w/tubing, went in hole with bit & casing scraper to 3624. SION.  2-1-00: POOH w/tubing & casing scraper, rigged up wireline- RIH w/gauge ring & junk basket to 3650', POOH, RIH & set CIBP @ 3595', POOH, RIH and dumped 35' of cement on top of CIBP. Ran cement bond log - top of cement @ 2428'. Ran GR/CNL from 3500-2400', RIH & set CIBP @ 3250', POOH, removed BOP, installed new wellhead-5000#. SION.  2-2-00: Rigged up reverse unit, circulated well w/2% KCL & tested to 1000#, rigged down hydro test, set packer @ 2898', tested backside for 15 mins held. Released packer & dropped down to 3186', SION.  2-3-00: Tested lines, pickled tubing, spotted acid, set packer @ 2885', removed BOP, installed prod. tree-tested to 5000#, rigged up wireline-perforated w/4 JSPF from 3156-3162' & 3190-3198', rigged down wireline. SION.  2-4-00: Rigged up reverse unit, tested lines, pumped 30 bbls 2% KCL water. Swabbed, SION.  2-7-00: Swabbed, rigged up BJ & pumped 1900# 20/40 sand in 2% KCL water. Swabbed, SION.  2-8-00: Rigged up wireline, tagged sand @ 3116', POOH, RIH w/bailer & dumped 5 gals cement ontop of sand. POOH, RIH & perforated w/4 JSPF @ 2941-2946',2984-2994',3018-3022',3044-3052',3077-3090'. Rigged down wireline, SION.  2-9-00: Swabbed. SI  Continued on page attached.									
14. I hereby	certify that the foregoing is the party correct.		Ann E. Ritch	io					
Signed	My Tudalio	Title	Regulatory A			Date	3-6-2000		
(This sp	ace for Federal or State office use)								

BLM(6) Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements

TO GWW

Approved by \_\_\_\_\_\_ Conditions of approval if any:

G ZA 5 Kaggs 6B

Date

SORMETT NW BTW

RECEIVED

