Submit 3 Copies To Appropriate District			
District I	State of New Mexico		Form C-103
1625 N. French Dr., Hobbs, NM 87240	Energy, Minerals and Natural Resources		Revised March 25, 1000
District II 811 South First, Artesia, NM 87210	OII CONCEDUATION		WELL API NO.
District III	OIL CONSERVATION DIVISION		30-025-07867 5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	2040 South Pacheco		
2040 South Pacheco, Santa Fe, NM 87505	Santa Fe, NM 87505		6. State Oil & Gas Lease No.
······································			0. State Oil & Gas Lease No. 25104
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name:
1. Type of Well:	(I) FOR SOCH	
Oil Well Gas Well 2. Name of Operator	Other injecto	r	Eumont Hardy Unit
Permian Resources	Inc		8. Well No.
Address of Operator	, Inc.	5	
P. O. Box 590	-00		9. Pool name or Wildeat
4. Well Location	Midland, TX 79702		Eumont (Yates-7R-Q)
Unit Letter I :	660 feet from the No	orth_line and	660 feet from the West line
Section 31	Township 20S	Range 39E	\ T (D) (
阿斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯	10. Elevation (Show whether	DR RKR PT CP -	NMPM Lea County
Start will be for the analysis of the start	3317 (1)61		
11. Check A	Appropriate Box to Indicate	Nature of Notice	Report or Other Date
NOTICE OF IN	TENTION TO:	SI IP	SSECUENT DEDOCT OF
ERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	SSEQUENT REPORT OF:
EMPORARILY ABANDON 🔲	CHANGE PLANS		TILING CASING L
PULL OR ALTER CASING	MULTIPLE		ARANDONIATION
	COMPLETION	CASING TEST A	ND
OTHER:	· · · · · · · · · · · · · · · · · · ·	OFMENT JOB	
		OTHER: cas	ing integrity test
of starting any proposed work). or recompilation.	ed operations. (Clearly state all p. SEE RULE 1103. For Multiple	pertinent details, and ge Completions: Attac	ing integrity test give pertinent dates, including estimated date h wellbore diagram of proposed completion
20 min. test condu			-
Start PSI 520#		20."	
Tubing pressure	End PSI 5 e held at 1360#	20#	
Casing pressure	e neid at 1360# e: 0		
Surface pressur	e: 0 re: 0		
pressu			
Good Test!	\ /		
1050.			
nereby certify that the transmit			
nereby certify that the information	above is true and complete to the	e best of my knowleds	ge and belief.
GNATURE CONTRACTOR	\checkmark		
	Vasnicka TITLE	Geologist	DATE 01/29/01
pe or print name	Dave Krasn	ich.	
his space for State use)	- Nush	icka.	Telephone No. 915/685-01
,			
PPPROVED BY	TITLE		
conditions of approval, if any:			DATE