UNITED STATES DEPARTMENT OF THE INTERIOR

| | Support Source (10) 12 MI 122 | | |
|---|--|--|--|
| | 5. LEASE | | |
| | LC 031696 (b) | | |
| | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME | | |
| - | | | |
| | 7. UNIT AGREEMENT NAME | | |
| | ELIMONT HARDY | | |
| | 8. FARM OR LEASE NAME | | |
| | Eumons HAADA Clair | | |
| | 9. WELL NO. | | |
| | 5 | | |
| | 10. FIELD OR WILDCAT NAME | | |
| | ### ### ### ### ### ### ### ### ### ## | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | LEA N.M. | | |
| _ | 14. API NO. | | |
| | | | |

| GEOLOGICAL SURVEY | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME |
|--|---|
| SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a difference reservoir. Use Form 9–331–C for such proposals.) | 8. FARM OR LEASE NAME |
| 1. oil gas other NITCCTION WALL | 9. WELL NO. |
| 2. NAME OF OPERATOR | 5 |
| CONTINUENTAL DIA COMPANY | 10. FIELD OR WILDCAT NAME |
| 3. ADDRESS OF OPERATOR | Lumont YATES 7RIRS. 11. SEC., T., R., M., OR BLK. AND SURVEY OR |
| Box 460, 400, kl,M, 88240 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 1 | |
| below.) | SEC.31, T.205, R.38E |
| AT SURFACE: 660'FA/L & 660'FWL | 12. COUNTY OR PARISH 13. STATE |
| AT TOP PROD. INTERVAL: | LEA N.M. |
| | 14. API NO. |
| 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTIC REPORT, OR OTHER DATA | |
| REPORT, OR OTHER DATA | 15. ELEVATIONS (SHOW DF, KDB, AND WD) |
| REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: | 3502'DF, |
| TEST WATER SHUT-OFF | (NOTE: Report results of multiple completion or zone change on Form 9–330.) |
| CHANGE ZONES | |
| 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* SUBJECT WELL WAS Cleared but and acidized as follows. - RIG UP AND PULL FROM 3657' TO 3793' - CIRC. HOLE CLEAN., PHIL AIT. - GO IN HOLE WI PKR on 276" work steine, set PKR @ 3650'. - Acidized wi 2000 gals Mod 202 acid will relatives. IN Two equal stages. - divert hotween stages wil 1000 " rock salt & gallod Beine. - REI. PKR, PULL Fbq. - RAN TENSIM PKR on tbq. & circ. PKR. fluid. - HOOK WOI! UP. PLACE ON INJECTION | |
| Subsurface Safety Valve: Manu. and Type | Set @Ft |
| 18. I hereby certify that the foregoing is true and correct | |
| SIGNED Wee. a. Thelley Just TITLE Adamin. Sc | IPV DATE 8-7-78 |
| (This space for Federal or State | |

AUG: 8 - 1978

J. S. GEOLOGICAL SURVEY HOBBS, NEW MEXICO