UNITED STATES

UNITED STATES	5. LEASE LC-063458
DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or plug back to a different servoir. Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME NMFU 8. FARM OR LEASE NAME
1. oil gas other WATER INJECTION	9. WELL NO.
2. NAME OF OPERATOR CONOCO INC.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, N.M. 88240	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	
AT SURFACE: 1980 FNL + GGO FWL AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH:	14. API NO. 30-025-07882
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) SOLATE PERFS	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly st. including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertin 	ent to this work.)*
MIRU 6/7/84. REL PKR @ 5646. ATTEMPTS TO SET PKR @ 5870' TO ISOLATE PERFS FAILED. SET CIBP @ 5870' + PKR @ 5707! PMPD 45 SXS CLASS "H" W/TOO & 5854! RESQUEEZED W/50 SXS CLASS "H". REL PKR. DO CMT TO 5855! PMPD 50 SXS CLASS "H". DO CMT TO 5858! PRESSURE TESTED TO 850 PSI. DO CMT TO CIBP @ 5870! PUSHED CIBP TO GOI3' + DO TO TO RAN INT EQUIP W/PKR SET @ 5856! INTECTING 200 BWPD @ 1570 PSI 6/22/84. Subsurface Safety Valve: Manu. and Type	
A A A A B A B A B A B A B A B A B A B A	
APPROVED 8" CONDITIONS IN LEGISLATION AND APPROVED BY	

The second second second

AUG 1 7 1984

See Instructions on Reverse Side

Alstan, New MEXICO