

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S	
LAND OFFICE	
TRANSPORTER	OIL
PRODUCTION OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103  
(Rev 3-55)

## MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company <b>Roy H. Smith Drilling Co.</b>		Address <b>728 First Wichita National Bldg., Wichita Falls, Texas</b>	
Lease <b>State 14</b>	Well No. <b>1</b>	Unit Letter <b>14</b>	Section <b>22-S</b>
Date Work Performed <b>November 2, 1962</b>		Pool <b>undesignated</b>	Range <b>34-E</b>
		County <b>Lea County, New Mexico</b>	

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations    ☐ Casing Test and Cement Job    ☐ Other (Explain):  
☒ Plugging    ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Plugged and abandoned with plugs as follows:

No. 1    50 sacks @ 4100 to 3900', w/10# mud 3900' - 3450'  
 No. 2    25 sacks @ 3450 to 3350', w/10# mud 3350' - 1850')  
 No. 3    25 sacks @ 1850 to 1750', w/10# mud 1750' - 350'  
 No. 4    25 sacks @ 350 to 250', w/10# mud 250' - 20'

Plugs were displaced through drill pipe

Witnessed by <b>Roy H. Smith</b>	Position <b>Owner</b>	Company <b>Roy H. Smith Drilling Co.</b>
-------------------------------------	--------------------------	---

### FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

D F Elev.		T D		P B T D		Producing Interval		Completion Date	
Tubing Diameter		Tubing Depth		Oil String Diameter		Oil String Depth			
Perforated Interval(s)									
Open Hole Interval					Producing Formation(s)				

### RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

### OIL CONSERVATION COMMISSION

Approved by <i>John W. Runyan</i>	I hereby certify that the information given above is true and complete to the best of my knowledge.
Title	Name <i>Roy H. Smith</i>
Date	Position <b>Owner</b>
	Company <b>Roy H. Smith Drilling Co.</b>