

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

**HOBBS OFFICE O. G. C.**  
NEW MEXICO OIL CONSERVATION COMMISSION

**Dec 16 11 51 AM '66**

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>B-9445</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name _____
2. Name of Operator <b>Skelly Oil Company</b>	8. Farm or Lease Name <b>State "G"</b>
3. Address of Operator <b>P. O. Box 730, Hobbs, New Mexico</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>A</b> <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>East</b> LINE, SECTION <b>5</b> TOWNSHIP <b>22-S</b> RANGE <b>35-E</b> NMPM.	10. Field and Pool, or Wildcat <b>San Simon</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3623' DF</b>	12. County <b>Lea</b>

**Check Appropriate Box To Indicate Nature of Notice, Report or Other Data**

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <b>Plug and Abandon</b> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**Well plugged and abandoned in the following manner:**

1. Moved in and rigged up pulling unit; pulled rods and tubing.
2. Spotted 55-Sack Cement Plug from 4144' back to 3885'.
3. Attempted to pull 7"O.D. Casing and could not recover any.
4. Pushed plug inside 7"OD casing to 217' and filled back with rock and Calseal to 202'.
5. Spotted 40 sacks of cement from 202' to surface.
6. Spotted 60 sacks of cement between 7"OD casing and 16"OD casing set at 96'.
7. Installed 4" pipe in top of 7"OD Casing as dry hole marker.
8. All intervals not cemented were filled with heavy mud laden fluid.
9. Well plugged and abandoned December 14, 1966.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

(ORIGINAL SIGNED) **H. E. Aub**

SIGNED \_\_\_\_\_ TITLE **District Superintendent** DATE **December 15, 1966**

APPROVED BY **Leslie A. Clement** TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: