## NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

libers of Fige occ

## MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is com-

	1	Indicate Nature of Re	port by Checking Be	low	
REPORT ON BEGINNING DRILLING OPERATIONS	X	REPORT ON RES		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL		REPORT ON REC OPERATION	OMPLETION	REPORT ON (Other)	
		<b>Mar</b> (Date	sh 7, 1955	Midland, Te	XAS (Place)
Following is a report on	the work done	and the results obtaine	d under the heading n	noted above at the	
The Texas Com	pany		State New M	exico *BZ**	
Carper Drilli		ау	, Well No	in the SW 1/4 NE	
22-S., R. 35-E., NMP		t Gas	Pool,	Lea	Count
he Dates of this work were as	folows	See Below			
otice of intention to do the w	ork (was	not) submitted on For	m C-102 on	(Cross out incorrect words)	, 19
nd approval of the proposed p					
nd approval of the proposed p	lan (was			LTS OBTAINED	
Ran and cemente	lan XXX (was  DETAILED A	not) obtained.  ACCOUNT OF WORK  TD - 1730'  ats, 1722' of	done and resu - Anhy  f 8-5/8" cas	ing set at 1730	)' with
Ran and cemente 00 sacks 4% Jel 2-55. Pressured	d 56 Jois and 200	not) obtained.  ACCOUNT OF WORK  TD - 1730'  ats, 1722' or  sacks regular  1000 lbs. at	c done and result - Anhy  f 8-5/8" cast cement. Ct 6:00 A.M.	ing set at 1730 ompleted 5:00 F 3-4-55. No dra	op in
Ran and cemente 00 sacks 4% Jel 2-55. Pressured essure after 30	d 56 Join and 200 and 200 and	not) obtained.  ACCOUNT OF WORK  TD - 1730'  ats, 1722' or  sacks regular  1000 lbs. at	c done and result - Anhy  f 8-5/8" cast cement. Ct 6:00 A.M.	ing set at 1730 ompleted 5:00 F 3-4-55. No dra	op in
Ran and cemente 00 sacks 4% Jel 2-55. Pressured essure after 30	d 56 Join and 200 and 200 and	not) obtained.  ACCOUNT OF WORK  TD - 1730'  ats, 1722' or  sacks regular  1000 lbs. at	c done and result - Anhy  f 8-5/8" cast cement. Ct 6:00 A.M.	ing set at 1730 ompleted 5:00 F 3-4-55. No dra	op in
Ran and cemente 00 sacks 4% Jel 2-55. Pressured essure after 30	d 56 Jois and 200 and	not) obtained.  ACCOUNT OF WORK  TD - 1730'  ats, 1722' or  sacks regular  1000 lbs. at  Drilling co	Company)	ing set at 1730 ompleted 5:00 F 3-4-55. No dre t 6:30 A.M. 3-4	op in
Ran and cemente 00 sacks 4% Jel 2-55. Pressured essure after 30	d 56 Jois and 200 and 200 with minutes.	not) obtained.  ACCOUNT OF WORK  TD - 1730'  ats, 1722' or  sacks regular  1000 lbs. at  Drilling co	Company)  I hereby certify the to the best of my least of the least of my least of the least of my lea	ing set at 1730 ompleted 5:00 F 3-4-55. No dre t 6:30 A.M. 3-4  (Title at the information given abore knowledge.	op in
00 sacks 🎜 Jel	d 56 Jois and 200 and 200 with minutes.	not) obtained.  ACCOUNT OF WORK  TD - 1730'  ats, 1722' or  sacks regular  1000 lbs. at  Drilling co	Company)  I hereby certify the to the best of my least	ing set at 1730 ompleted 5:00 F 3-4-55. No dre t 6:30 A.M. 3-4  (Title at the information given abore knowledge.  t. Dist. Supt.	ve is true and comple
Ran and cemente 00 sacks 4% Jel 2-55. Pressured essure after 30	d 56 Jois and 200 and 200 with minutes.	not) obtained.  ACCOUNT OF WORK  TD - 1730'  ats, 1722' or  sacks regular  1000 lbs. at  Drilling co	Company)  I hereby certify the to the best of my learner to the best o	ing set at 1730 ompleted 5:00 F 3-4-55. No dre t 6:30 A.M. 3-4  (Title at the information given abore knowledge.	ve is true and comple