

COPIES RECEIVED	
TRIBUTION	
FE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5 State Oil & Gas Lease No. 13137	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Water Injection Well</u>		7. Unit Agreement Name <u>Jalmat Field Yates Sand Unit</u>
2. Name of Operator <u>Gulf Oil Corporation</u>		8. Farm or Lease Name
3. Address of Operator <u>Box 670, Hobbs, New Mexico 88240</u>		9. Well No. <u>146</u>
4. Location of Well UNIT LETTER <u>B</u> , <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>1650</u> FEET FROM THE <u>East</u> LINE, SECTION <u>23</u> TOWNSHIP <u>22-S</u> RANGE <u>35-E</u> NMPM.		10. Field and Pool, or Wildcat <u>Jalmat</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3593' GL</u>		12. County <u>Lea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Plug and Abandon</u> <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3981' TD- 3970' PB.

Pull injection equipment. Set CI BP at 3780' and cap with 5 sack cement plug from BP to 3730'. Displace hole with water containing 25 sacks of gel per 100 barrels of water. Spot 15 sack Class C cement plug from 2000' to 1850', across top of salt. Load hole with heavy mud. Spot 50' cement plug from 50' to surface. Install dry hole marker and clean location.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B. Barbary TITLE Area Engineer DATE May- 6, 1974

APPROVED BY [Signature] TITLE [Signature] DATE May 7 1974

CONDITIONS OF APPROVAL, IF ANY: