NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New OMERSOOFFICE OCC

MISCELLANEOUS REPORTS ON WELLS 10: 07

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is com- \mathbf{p} re ir

	ons of the Commission. Indicate Nature of Report	by Checking Below		
REPORT ON BEGINNING DRILLING OPERATIONS	REPORT ON RESULT OF CASING SHUT-OF	OF TEST	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL	REPORT ON RECOMP OPERATION	LETION	REPORT ON (Other)	
	June 5	i, 19 5 6	Artesia, New Me	
Following is a report on the wor	k done and the results obtained un	der the heading noted	above at the	
Carper Drilling Compan	y. inc.	C	arper-Rande	
Carper Drilling Compan	y, İns. , W	ell No 2A i	n the	ec 24
225 , R. 35E , NMPM.,	Jalmet	Pool,	Lea	Count
The Dates of this work were as folows:			***************************************	
Notice of intention to do the work (#	(was not) submitted on Form C-	102 on(Cr	oss out incorrect words)	, 19
and approval of the proposed plan (
DET	AILED ACCOUNT OF WORK DO	NE AND RESULT	S OBTAINED	
	AILED ACCOUNT OF WORK DO			_
	J-55 cosing, landed @			ks
Ren 3835' of 5 1/2" 14	J-55 casing, landed @ 3	3847' on 5-25-5	6. Cemented w/600 sac	
Ren 3835' of 5 1/2" 14	J-55 casing, landed @ :	3847' on 5-25-5 ourton did the co	6. Cemented w/600 sac ementing. On May 26,	the casin
Ren 3835' of 5 1/2" 14	J-55 casing, landed @ :	3847' on 5-25-5 ourton did the co	6. Cemented w/600 sac ementing. On May 26,	the casin
Ren 3835' of 5 1/2" 14 posmix 4% Gel. Plug of tested with 1100# PSI fo	J-55 casing, landed @ : down @ 10:00 P.M. Hallil or 30 minutes. No drop in	3847' on 5–25–5 ourton did the co pressure was rep	6. Cemented w/600 sac ementing. On May 26, certed. Mud was then di	the casin
Ren 3835' of 5 1/2" 14 posmix 4% Gel. Plug of tested with 1100# PSI fo	J-55 casing, landed @ :	3847' on 5–25–5 ourton did the co pressure was rep	6. Cemented w/600 sac ementing. On May 26, certed. Mud was then di	the casin
Ren 3835' of 5 1/2" 14 posmix 4% Gel. Plug of tested with 1100# PSI fo	J-55 casing, landed @ : down @ 10:00 P.M. Hallil or 30 minutes. No drop in was begun. One 20' joint	3847' on 5-25-5 purton did the co pressure was rep of casing was ru	6. Cemented w/600 sac menting. On May 26, orted. Mud was then di n below the float collar	the casin
Ren 3835' of 5 1/2" 14 poemix 4% Gel. Plug of tested with 1100# PSI fo	J-55 casing, landed @ : down @ 10:00 P.M. Hallil or 30 minutes. No drop in	3847' on 5-25-5 purton did the co pressure was rep of casing was ru	6. Cemented w/600 sac menting. On May 26, orted. Mud was then di n below the float collar	the casin
Ren 3835' of 5 1/2" 14 posmix 4% Gel. Plug of tested with 1100# PSI for oil. Completion work	J-55 casing, landed @ : down @ 10:00 P.M. Hallil or 30 minutes. No drop in was begun. One 20' joint	3847' on 5-25-5 purton did the co pressure was rep of casing was ru	6. Cemented w/600 sac menting. On May 26, orted. Mud was then di n below the float collar	the casin
Ren 3835' of 5 1/2" 14 posmix 4% Gel. Plug of tested with 1100# PSI fo oil. Completion work of float collar was not dri	J-55 casing, landed @ : down @ 10:00 P.M. Hallih or 30 minutes. No drop in was begun. One 20' joint	3847' on 5-25-5 purton did the co pressure was rep of casing was ru ant in the casing	6. Cemented w/600 sac amenting. On May 26, acrted. Mud was then di a below the float collar	the casin splaced v
Ren 3835' of 5 1/2" 14 poemix 4% Gel. Plug of tested with 1100# PSI for oil. Completion work of float collar was not dri A. L. Piero	J-55 casing, landed @ : down @ 10:00 P.M. Hallil or 30 minutes. No drop in was begun. One 20' joint lied which left.20' of came	3847' on 5-25-5 curton did the co- pressure was rep of casing was ru ent in the casing	6. Cemented w/600 sac menting. On May 26, orted. Mud was then di n below the float collar	the casin splaced t and the
Ren 3835' of 5 1/2" 14 posmix 4% Gel. Plug of tested with 1100# PSI for oil. Completion work of float collar was not drift. A. L. Piero	J-55 casing, landed @ : down @ 10:00 P.M. Hallil or 30 minutes. No drop in was begun. One 20' joint lied which left.20' of came	3847' on 5-25-5 curton did the cu pressure was rep of casing was ru ont in the casing	6. Cemented w/600 sac nmenting. On May 26, norted. Mud was then di n below the float collar . Mgr. of retary d	the casin
Ren 3835' of 5 1/2" 14 poemix 4% Gel. Plug of tested with 1100# PSI for oil. Completion work of float collar was not drift. A. L. Piero (Name Approved:	J-55 casing, landed @ down @ 10:00 P.M. Hallillor 30 minutes. No drop in was begun. One 20' joint which left.20' of came	3847' on 5-25-5 curton did the co- pressure was rep of casing was ru ont in the casing ling Co., Inc.	6. Cemented w/600 sac nmenting. On May 26, norted. Mud was then dis n below the float collar 	the casir uplaced to and the
Ren 3835' of 5 1/2" 14 poemix 4% Gel. Plug of tested with 1100# PSI for oil. Completion work of float collar was not drift. A. L. Piero (Name Approved:	J-55 casing, landed @ : down @ 10:00 P.M. Hallil or 30 minutes. No drop in was begun. One 20' joint lied which left.20' of came	on 5-25-5 curton did the corpressure was reported to the casing was ruled in the casing ling Co., Inc.	6. Cemented w/600 sac nmenting. On May 26, norted. Mud was then dis n below the float collar 	the casin
Ren 3835' of 5 1/2" 14 poemix 4% Gel. Plug of tested with 1100# PSI for oil. Completion work of float collar was not drift. A. L. Piero (Name Annoyed:	J-55 casing, landed @ down @ 10:00 P.M. Hallillor 30 minutes. No drop in was begun. One 20' joint was begun. One 20' joint which left. 20' of come	ourton did the corpressure was reported for the casing was runned in the casing ling Co., inc.	Mgr. of rotary determined in the information given above is true owledge.	the casin
Ren 3835' of 5 1/2" 14 poemix 4% Gel. Plug of tested with 1100" PSI for oil. Completion work of float coller was not dri Witnessed by A. L. Piero (Name Approved:	J-55 casing, landed @ down @ 10:00 P.M. Hallillor 30 minutes. No drop in was begun. One 20' joint alled which left.20' of came and compared to the compared to	ourton did the corpressure was reported for the casing was runting the casing ling Co., inc. To the best of my known and the best of my known vice-Prosition.	Mgr. of rotary determined in the information given above is true owledge.	the casin

- - -

the state of the s

en de filosofie de la companya del companya de la companya del companya de la com

Andrew Community