

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRI
(Other instruction
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR <i>Conoco Inc</i>		8. FARM OR LEASE NAME <i>Lockhart B-1</i>
3. ADDRESS OF OPERATOR <i>P.O. Box 460 - Hobbs, NM 88240</i>		9. WELL NO. <i>3</i>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <i>1980' FSL & 1980' FEL - Unit Letter J</i>		10. FIELD AND POOL, OR WILDCAT <i>Arrowhead Craiburg</i>
14. PERMIT NO. <i>30-025-08724</i>		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <i>1-22S-36E</i>
15. ELEVATIONS (Show whether DF, RT, GR, etc.)		12. COUNTY OR PARISH <i>Lea</i>
		13. STATE <i>NM</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) *Clean Out, Log & Acidize* ☒

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MIRU on 3/27/87. Clean out fill 3767'-3802'. Drill new 4 3/4" hole 3802'-3840'. Tag at 3805'. Circ hole to TD w/ 9" brine to 3840'. Set pkr at 3640'. Pressure csq to 500 psi. Acidize w/ 20 bbls 15% HCL-NE-FE acid. Pump 500 bbls rock salt in 2 bbls gelled 10 PP9 brine. Pump 30 bbls 15% HCL-NE-FE. Repeat block, pump 50 bbls 15% HCL-NE-FE, repeat block, pump 50 bbls 15% HCL-NE-FE acid, overflush w/ 50 bbls TFW. Swab well. Rel pkr. Place well on production. Completed work on 4/7/87.

ACCEPTED FOR RECORD

SJS
JUN 26 1987

CARLSBAD, NEW MEXICO

RECEIVED
JUN 26 11 00 AM '87
CARLSBAD RESOURCE
AREA HEADQUARTERS

18. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]* JF FINNEY

TITLE *Administrative Supervisor* DATE *6-16-87*

(This space for detail of State office use)

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See instructions on Reverse Side

Title 18 USC Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlsbad(6) ARCO(2) Amoco(2) Chevron(1) File

RECEIVED

JUL 2 1987

CCD
HOBBS OFFICE