Submit 3 Copies To Appropriate District State of New Mexico Form C-103 Office Energy, Minerals and Natural Resources Revised March 25, 1999 District I WELL API NO. 1625 N. French Dr., Hobbs, NM 87240 District II 30-025-08735 OIL CONSERVATION DIVISION 811 South First, Artesia, NM 87210 5. Indicate Type of Lease 2040 South Pacheco District III 1000 Rio Brazos Rd., Aztec, NM 87410 STATE 😠 FEE \square Santa Fe, NM 87505 District IV 6. State Oil & Gas Lease No. 2040 South Pacheco, Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: ARROWHEAD GRAYBURG UNIT Oil Well Gas Well Other 2. Name of Operator 8. Well No. Chevron U.S.A. Inc. 3. Address of Operator 9. Pool name or Wildcat P.O. Box 1150 Midland, TX 79702 ARROWHEAD; GRAYBURG 4. Well Location 2310 Unit Letter SOUTH 990 feet from the line and feet from the line Section Township 02 **22**S Range 36E **NMPM** County LEA 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK **ALTERING CASING** TEMPORARILY ABANDON **CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND **ABANDONMENT** PULL OR ALTER CASING **MULTIPLE** CASING TEST AND COMPLETION **CEMENT JOB** OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. CHEVRON PROPOSES TO TA PER THE ATTACHED PROCEDURE HE CONVER OUT OF HE BOTTER IN HOURS SHOW TO THE THERWHAG OF MUSCLMS CHRATIONS FOR THE C-103 TO BE APPROVED. I hereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE REGULATORY O.A. _DATE_ 2/14/01

Telephone No.

(915)687-7148

Type or print name J. K. RIPLEY

(This space for State use)

Conditions of approval, if any:

APPROVED BY

S2-T22S & R36E Arrowhead Grayburg Unit Lea County, New Mexico

PROCEDURE TO TEMPORARILY ABANDON WELL:

Notify OCD/BLM 24 hrs prior to work commencing.

- 1. Verify anchors have been set & tested.
- 2. MIRU PU. ND WH. NU BOP.
- 3. TOH w/tbg. TIH w/4-3/4" bit, csg scraper, & WS. Make bit trip to 3700'. POH.
- 4. Set CIBP @ 3650', on top of the casing shoe. Dump 3 sx Class 'C' cmt on CIPB.
- 5. TIH w/WS to TOC. Circulate csg w/corrosion inhibited pkr fluid. TOH.
- 6. Perform MIT (500 PSI for 30 min.).
- 7. ND BOP. NU WH. RD PU.
- 8. Clean and clear location.

T. Love 687-7645

CURRENT WELL DATA SHEET

FIELD: Arrowhead

WELL NAME: AGU No. 172

FORMATION: Grayburg

LOC: 2310' FSL & 990' FWL

TOWNSHIP: 22-S RANGE: 36-E SEC: 2 COUNTY: Lea


GL: 3539' KB to GL:

CURRENT STATUS: Producer API NO: 30-025-08735

STATE: NM

DF to GL:

CHEVNO: FA9795



AGU

5-1/2", 15 #/ft, csg @ 3702' w/ 200 sxs cmt. TOC @ 1894' by calc. 7" hole.

OLD TD @ 3820'

PBTD 4058'

PBTD 4058 TD 4100'

FILE: WBS172.XLS MRV: 12/23/97

PROPOSED WELL DATA SHEET

FIELD: Arrowhead

WELL NAME: AGU No. 172

FORMATION: Grayburg

LOC: 2310' FSL & 990' FWL


TOWNSHIP: 22-S RANGE: 36-E SEC: 2


COUNTY: Lea STATE: NM

KB to GL: DF to GL:

GL: 3539' CURRENT STATUS: Producer KB to GL: API NO: 30-025-08735

CHEVNO: FA9795





TD 4100'

FILE: WBS172.XLS MRV: 12/23/97