

to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells) 30-025-08739	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. N/A	
7. Lease Name or Unit Agreement Name ARROWHEAD GRAYBURG UNIT	
8. Well No. 169	
9. Pool name or Wildcat ARROWHEAD/GB	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> CONVERT TO WATER INJECTOR	
2. Name of Operator CHEVRON U.S.A. INC.	
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE	
4. Well Location Unit Letter I Section 2 : 1980 Feet From The SOUTH Line and 660 Feet From The EAST Line Township 22S Range 36E NMPM LEA County	
10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3530' GR	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
 PULL OR ALTER CASING ☐
 OTHER: **CONVERT TO WTR INJ** ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTER CASING ☐
 COMMENCE DRILLING OPNS. ☐ PLUG AND ABAN. ☐
 CASING TEST AND CMT JOB ☐
 OTHER: ☐

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including
 estimated date of starting any proposed work) SEE RULE 1103.

WE PROPOSE TO:

POH W/RODS & PMP, ND WH, NU BOP. TST CSG TO 500 PSI F/30 MINUTES. REPAIR
 CASING LEAK IF NECESSARY. FISH MUD ANCHOR JOINT. DEEPEN WELL 75' TO 3915'. CIRC
 CLEAN. PERF 3715-3730', 22 HOLES, 2 JHPF. ACDZ PERFS 3715-3839 W/2300 GALS 15% NEFE HCL.
 SWAB BACK LOAD. CLEAN OUT TO PBTD, CIRC CLEAN. RUN 2-3/8 DUOLINE FIBERGLASS TBG
 & SET 5-1/2 INJECTION PKR @3650'. TST ANNULUS TO 300 PSI F/30 MINS.
 PLACE WELL ON INJECTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Nita Rice

TITLE

TECHNICAL ASSISTANT

DATE: 3/30/93

TYPE OR PRINT NAME

NITA RICE

TELEPHONE NO. (915)687-7436

APPROVED BY

APPROVED BY JERRY SEXTON

DATE

APR 02 1993

CONDITIONS OF APPROVAL, IF ANY

RECEIVED

APR 01 1997

ODD HOUSE STAMP