

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

|                                                                                                      |
|------------------------------------------------------------------------------------------------------|
| 5a. Indicate Type of Lease<br>State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No.<br><b>B-1534</b>                                                        |
| 7. Unit Agreement Name                                                                               |
| 8. Farm or Lease Name<br><b>State J-2</b>                                                            |
| 9. Well No.<br><b>10</b>                                                                             |
| 10. Field and Pool, or Wildcat<br><b>Arrowhead Grayburg</b>                                          |
| 12. County<br><b>Dea</b>                                                                             |

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

|                                                                                                                                                                                                          |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>                                                                                         |
| 2. Name of Operator<br><b>Conoco Inc.</b>                                                                                                                                                                |
| 3. Address of Operator<br><b>P.O. Box 460 - Hobbs, New Mexico 88240</b>                                                                                                                                  |
| 4. Location of Well<br>UNIT LETTER <b>E</b> <b>1980</b> FEET FROM THE <b>north</b> LINE AND <b>990</b> FEET FROM<br>THE <b>west</b> LINE, SECTION <b>2</b> TOWNSHIP <b>22S</b> RANGE <b>36E</b> N.M.P.M. |
| 15. Elevation (Show whether DF, RT, GR. etc.)                                                                                                                                                            |

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:

|                                                |                                                                       |
|------------------------------------------------|-----------------------------------------------------------------------|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/>                             |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>                                 |
| PULL OR ALTER CASING <input type="checkbox"/>  | OTHER <b>Return to Production</b> <input checked="" type="checkbox"/> |

## SUBSEQUENT REPORT OF:

|                                                      |                                               |
|------------------------------------------------------|-----------------------------------------------|
| REMEDIAL WORK <input type="checkbox"/>               | ALTERING CASING <input type="checkbox"/>      |
| COMMENCE DRILLING OPNS. <input type="checkbox"/>     | PLUG AND ABANDONMENT <input type="checkbox"/> |
| CASING TEST AND CEMENT JOBS <input type="checkbox"/> | OTHER <input type="checkbox"/>                |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU. Remove 1st of Hbg in wellhead. Run bit to top of liner at 3662' & POOH. Set CIBP at 3660' test to 1000 psi via plcr. POOH. Dump 1/2 sk Cal-Seal plug on top CIBP at 3655'-3660'. Set whipstock on Cal-Seal plug at 3655'. Release setting mill, circ hole w/mud, & begin cutting window in csq. POOH. Drill out OH to 3945'. Circ hole. POOH. Log well from TD to 3300' & POOH. Run 4" flush it liner & equipment into hole. Liner shoe at 3945'. Circ hole & set liner hanger. Batch mix 20 sxs class "C" cement w/2% CaCl<sub>2</sub>. Pump 20 sxs cement to cmt liner in place. Flush w/18 bbls 2% KCL TFW. POOH. Drill out cement to top of liner at 3564' & POOH. Pressure test csq to 500 psi. (elf test fails, a squeeze procedure will follow. Drill out landing collar & cement to 3940'. POOH. Log well from 3940' to 3300' & correlate to existing logs. POOH. Perf 3745'-3862' w/4j5pF for total of 192 shots & POOH

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED **DF FINNEY** TITLE **Administrative Supervisor**

DATE **8/31/88**

ORIGINAL SIGNED BY **JERRY SEXTON**

APPROVED BY **DISTRICT 1 SUPERVISOR**

TITLE

DATE **SEP 6 '88**

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

SEP 6 1981

ON  
MORBS OFFICE

State J-2 No. 10  
Pg 2

G1H w/ pkr & set at 3650'. Acidize Permian Grayburg 3745'-3862' w/ 90 bbls 15% HCL-NE-FE acid inhibited for 24 hrs at 100°F plus 100 ball sealers and 400# graded rock salt mixed in 4 bbls gelled 9# brine in 3 equal stages. Flush w/ 50 bbls 9# brine. Release pkr. Riset at 3730' & swab back load. Release pkr & POOH. G1H. Land SN at 3850'. Run rods & pump and place well on production. For further information please contact Jay Vashler at 397-5866.