Supmit 3 Copies to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revisied 1-1-89

District Office	OIL CC	NSERVATIO	N DIVISION						
		P.O. Box 2088							
DISTRICT I	Sar	nta Fe, New Mex	ico 87504-2088						
P.O. Box 1980, Hobbs, NM 88240									
DISTRICT II				API NO. (assigne 30-025-08	a by OCD on New V 754	Velis)			
P.O. Drawer Dd, Artesia, NM 88210)			5. Indicate Type					
DISTRICT III 1000 Rio Brazos Rd., Aztec, Nm 87410					STATE X FEE				
1000 1110 01.0202 11.01, 1.2001				6. State Oil &	Gas Lease No.				
				N/A					
9	UNDRY NOTICES	AND REPORTS OF	N WELLS						
JOO NOT LICE TH	IS TORM FOR PROPOS	ALS TO DRILL OR TO	DEEPEN OR PLUG BACK	7. Lease Name	or Unit Agreement I	vame	*******		
(DO NOT USE IN	FFERENT RESERVOIR.	USE "APPLICATION F	OR PERMIT"						
(FORM C-101) FOR SUCH PROPOSALS.)					HARRY LEONARD (NCT-D)				
1. Type of Well:									
OIL	GAS								
WELL X	WELL OTHER	R							
2. Name of Operator				B. Well No.	2				
CHEVRON U.	S.A. INC.				3				
3. Address of Operator	9. Pool name or Wildcat JALMAT GAS								
P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE					AS				
4. Well Location Unit Letter K	1980	Feet From The	SOUTH Line and	1980	Feet From The	WEST	Line		
Section 3		Township 22S	Range	36 E	NMPM	LEA	County		
Section		10. Elevation(Show w	hether DF, RKB, RT, GR, etc	.)					
			3579' GL						
11		x to Indecate Nature	of Notice, Report, or Oth	er Data					
NOTICE OF IN	NTENTION TO:		SUBSEQUENT	REPORT OF		r	_		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIA	AL WORK	_	ALTER CASING	ļ			
TEMPORARILY ABANDON	CHANGE PLANS	СОММЕ	NCE DRILLING OPNS.	_	PLUG AND ABAN.	. [
PULL OR ALTER CASING]	CASING	TEST AND CMT JOB	<u> </u>		г	ΧĪ		
OTHER:		OTHER:	CONVERT FROM				<u> </u>		
			SINGLE PRODU	CER					
12. Describe Proposed or Comple	ted Operations(Clearly state	all pertinent details, and g	ive pertinent dates, including						

esticated date of starting any proposed work) SEE RULE 1103.

WORK PERFORMED 4-26 THUR 4-30-93 MIRU PU, POOH W/RODS . LEFT PMP IN HOLE & PMP 50 BBLS CKF DN BACKSIDE TO KILL JALMAT ZONE. NU BOP, CUT TBG @ 3675 & PULL 121 JTS & CJ. SET CIBP @ 3671%, CAP W/35' CEMENT. ND BOP, NU WH, SWAB BACK LOAD & PLACE WELL BACK ON PRODUCTION

SIGNITURE	ita is in and complete	e to the best of my knowledge and belief. TITLE TECHNICAL ASSISTANT	DATE:	6/7/93	
TYPE OR PRINT NAME	NITA RICE		TELEPHONE NO. (915)687-7436		
APPROVED BY	PROVED BY DESCRIPTION OF THE STATE OF THE ST		DATE	IUN 15 1993	

JUN 1 4 1993

CCD HOBBS OFFICE