Dually completed as South Sunice and Jalmat as follows:

- 1. Treated open hole formation from 3805-3900! with 10,000 gallons gelied lease oil with 1# sand per gallon. Injection rate 15.8 bols per minute. Swabbed and well kicked off.
- 2. Ran 5-1/2" Model D production packer on wire line at 3750'. Man 2-3/8" tubing with GOT circulating valve in closed position at 3844', seal nip le at 3813', Model C-1 receptacle seal unit at 3748' and GOT circulating valve in closed position at 3716'. Tested tai pipe and casing with 500# for 30 minutes, no drop in pressure. Fulled 2-3/8" tubing and seal nipple.
- 3. Perforated 5-1/2" casing from 3200-3230', 3245-3265', 3302-3346', 3370-3400', 3592-3602' and 3618-3650' with 2, 1/2" jet holes per foot. Ran 2-7/8" tubing with retrievable bridge plug at 3686' and full sore packer at 3178'. Treated formation thru perforations in 5-1/2" casing from 3802-3400' with 7500 gallons lease crude with 1# sand per gallon. Heset bridge plug at 3286' and packer at 3184'.
- 4. Treated formation thru perforations in 5-1/2" casing from 3200-3265' with 300 gallons 15% acid. Swabbed and well kicked off. Treated formation thru perforations in 5-1/2" casing from 3200-3346? with 10,000 gallons lease oil with 1# sand per gallon, last 1000 gallons contained radio active sand. Swabbed and well kicked off.
- 5. Pulled 2-7/8" tubing, bridge plug and packer. "eran 2-3/8" tubing and seal nipple, latened into receptacle at 3750'. Opened circulated valve at 3716'. Swambed and well kicked off. Closed circulating valve at 3716'.
- 6. Opened circulating valve at 3844'. Swabbed and well kaaked off. Jalmat zone closed in.

1

.

· Set in the

•