

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ For ☐
5. State Oil & Gas Lease No.
B-229-1

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER	7. Unit Agreement Name
2. Name of Operator <u>Gulf Oil Corp.</u>	8. Name of Lease 1-400 <u>Quinn Waterflood</u>
3. Address of Operator <u>P. O. Box 670, Hobbs, NM 88240</u>	9. Well No. <u>9</u>
4. Location of Well UNIT LETTER <u>C</u> <u>66C</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>4</u> TOWNSHIP <u>22S</u> RANGE <u>36E</u> N.M.P.M.	10. Field and Pool, or Wildcat <u>1. Eunice</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3589' GL</u>	12. County <u>Lea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER ☒ <u>Recompletion</u>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH w/ plug + pkr. Dril out cmt ret + cmt to 3626'. Dril out CIBP's @ 3670' + 3760'. Set RBP @ 3100'. Obtain circ out 878". Pump 2 sil sand on RBP. Set cmt ret @ 800'. Pump 4CC 24, got circ out 858". Sq 800#. Dril ret + cmt. Circ clean. POH w/ RBP. Dril CIBP @ 3770'. Clean out to 3911'. Acy @ 3730' w/ 4230 gals 15% NEFE. Entire job on vac. Swab. Perf 3764-66' + 3777-79' w/ 415H. Acy w/ 1000 gals 15% NEFE. AP 200#. Clean out to 3911'. GIN w/ plug, slide down. Close SS + retrieve blank plug in pkr. GIN w/ pump + rods. Connect circ. Work performed 11-26 thru 12-30-84.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED RD Pite TITLE AREA ENGINEER DATE 1-3-85

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

APPROVED BY _____ TITLE _____ DATE JAN - 7 1985

CONDITIONS OF APPROVAL IF ANY:

RECEIVED

JAN - 4 1985

C. J. G.
HOBBS OFFICE