

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name	
State "A" A/c-2	
9. Well No.	
27	
10. Field and Pool, or Wildcat	
South Eunice	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/>	GAS WELL <input checked="" type="checkbox"/>	OTHER- Dual
2. Name of Operator		
TEXAS PACIFIC OIL COMPANY		
3. Address of Operator		
P. O. Box 1069 - Hobbs, New Mexico		
4. Location of Well		
UNIT LETTER P	660	FEET FROM THE East LINE AND 660 FEET FROM THE South LINE, SECTION 5 TOWNSHIP 22-S RANGE 36-E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

No Record

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Disconnect well, pulled rods and tubing.
2. Ran Baker Model "D" w/punch out plug and set in 5-1/2" liner at 3520'.
3. Ran collar log and perforated 3055-3076-3110-3152-3168-3178-3209-3230-3243-3250-3290-3296-3309-3355 (3/8" holes).
4. Set packer at 2719' and acidized w/2000 gal W.E. Acid.
5. S.O.T. w/20,000 oil and 20,000# sand w/Adomite. Tested.
6. Ran long string tubing w/sleeve valve and packer.
7. Acidized Queens zone w/1000 gal acid.
8. Run short string tubing and seal assembly and pulled blanking plug.
9. Run rods and set lower zone pumping

(See No. 10 on back)

Original signed by:

SIGNED John H. Hendrix TITLE District Engineer DATE February 1, 1965

APPROVED BY TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

17. Describe Proposed or Completed Operations (continued)

10. Complete well as a Jalmat Gas and South Eunice Oil Dual. (Gas in annulus and oil in tubing)