## NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

## **MISCELLANEOUS NOTICES**

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

		Indicate Nature of Notice by	Checking Bel	OW	
Notice of Intention to Change Plans		Notice of Intention to Temporarily Abandon Well		Notice of Intention to Drill Deeper	
Notice of Intention to Plug Well		Notice of Intention to Plug Back		Notice of Intention to Set Liner	
Notice of Intention to Squeeze		Notice of Intention to Acidize		Notice of Intention to Shoot (Nitro)	
Notice of Intention to Gun Perforate	X	Notice of Intention (Other) Sandoll Frac	x	Notice of Intention (Other)	
OIL CONSERVATION SANTA FE, NEW M		Hobbs, New (Place)	Mexico	October	20, 1958
Gentlemen:		(Fisce)		(Date)	,
Following is a No	otice of Intention to d	o certain work as described below	at the		
nclair 011 a	Company or Operato	y State 157	нди	Well No <b>2</b>	inG
(40-acre Subdivision	4 of Sec5	", T. 228 , R 361	NMPM.,	South Eunice	Poo
Lea	Co	unty.			
PARAGE SA	(FOLLOW	LL DETAILS OF PROPOSEI	JLES AND R	EGULATIONS)	- <b></b>
PROPOSE TO:	(FOLLOW Perforate 5.		DE 3814-	egulations) -3824 w/4 jet sh	ots per foc
PROPOSE TO:	Perforate 5. Set Baker Re	-1/2" OD Casing from	om 3814- Plug at	-3824 w/4 jet sh	ots per foc
PROPOSE TO:	Perforate 5. Set Baker Ro	v instructions in the Ru-1/2" OD Casing fro etreivable Bridge F	om 3814- Plug at 4 w/500	3824 w/4 jet sh 3828. gals mud acid.	
Approved	FOLLOW Perforate 5. Set Baker Ro Acidise Per: Sandoil frac	v instructions in the ru1/2" OD Casing fro etreivable Bridge F forations 3814-3824 e Perforations 3814	om 3814- Plug at  # w/500 4-3824 w	3824 w/4 jet sh 3828. gals mud acid.	1 & 15,000
	FOLLOW Perforate 5. Set Baker Roading Per: Sandoil fractional.	v instructions in the ru1/2" OD Casing fro etreivable Bridge F forations 3814-3824 e Perforations 3814- By	Sinclai	3824 w/4 jet sh 3828'. gals mud acid. 1/15,000 gals of	1 & 15,000
Approved	FOLLOW Perforate 5. Set Baker Roacidise Per: Sandoil fractions and.	v instructions in the ru1/2" OD Casing fro etreivable Bridge F forations 3814-3824 e Perforations 3814- By	Sinclai	-3824 w/4 jet sh 3828.  gals mud acid.  1/15,000 gals of	1 & 15,000
ApprovedExcept as follows:	FOLLOW Perforate 5. Set Baker Roacidise Per: Sandoil fractions and.	v instructions in the ru1/2" OD Casing fro etreivable Bridge F forations 3814-3824 e Perforations 3814- By	Sinclai	3824 w/4 jet sh 3828.  gals mud acid.  1/15,000 gals of  Company or Operator  Supt.  Communications regarding we	1 & 15,000

Orig &2cc: OCC; cc:FHR, HFD, File