

State "A" A/C-2 #46
Lea County, New Mexico

- 10/16/86 Latch fish back off rods tbg 100% stuck at 2525' 100% free at 2483' chem cut tbg at 2473' POH LD 2-3/8" prod tbg TIH w/5-3/4" overshot, bumper sub, jars & DCs on 2-7/8" WS latch fish at 2473' jar on fish 2-1/2 hrs jar free
- 10/17/86 POH rec 15' 2-3/8 tbg, tag & wash over fish 2487-2509 rec trace metal & scale 2509-2510 (3/4 HR) all metal returns
- 10/20/86 Tag & wash over fish 2510-2518 rec metal shoe quit cutting wash over fish 2518-2524 rec scale & metal lost 100% returns @ 2524 fish fell to BTM, latch fish at 2690'
- 10/21/86 Rec all fish TIH w/7" RBP & pkr on 2-7/8" WS to 650'
- 10/22/86 Set RBP @ 3687, test RBP to 1000-OK, isolated csg leak 2512-2542 EIR 1/2 BPM @ 2500, tested surf - 2512 and 2542-3687 to 1000-OK, retrv. RBP & POH, RIH w CIBP on, 2-7/8 W.S., set CIBP @ 3687
- 10/23/86 RIH w/7" cmt ret on 2-7/8 tbg set ret 2478 trap 500# on csg Howco squeeze csg leak 2512-2542 w/80 sks "C" w/4# salt 3/10% Ha-ad-9 disp 75 sks below ret FP 1400 snap out rev out 5 sks POH LD 2-7/8 tbg ND BOP NU WH Rig Rel