	IITED ENT C LOGIC	TRIPLICATE) STATES F THE INTERIOR AL SURVEY STED 17 222 D REPORTS ON	Lease No Cunit	Service CII S
NOTICE OF INTENTION TO DRILL	X	SUBSEQUENT REPORT OF WATER SUBSEQUENT REPORT OF SHOOT SUBSEQUENT REPORT OF ALTER SUBSEQUENT REPORT OF ALTER SUBSEQUENT REPORT OF ABAND SUPPLEMENTARY WELL HISTORY	SHUT-OFF ING OR ACIDIZI ING CASING ILLING OR REP/ NONMENT	ING
(INDICATE ABOVE BY CHECK M Well No. 2 is located 1980 ft. fr			ury 16	ne of sec

Budget Bureau 42-R358.3.

-

(Meridian) (Range) (Twp.) (14 Sec. and Sec. No.) Hes Herico Les fouth hunice -----..... (State or Territory) (County or Subdivision) (Field)

The elevation of the derrick floor above sea level is 3561 ft.

22-3

NE ST 6

DETAILS OF WORK

12/X

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, coment-ing points, and all other important proposed work)

Closson So. 2 has been shut-in. It is proposed to have in a workever whit, clean-out to bottom, log, plug back and the possible producing formations tested and acidized or reperforsted as necessary. The azount of open hole to be plugged off will be setermined during the progress of the work as well as the other necessary work to restore this well to producing status. The approval of the UNGS will be secured if my change in the proposed remedial work is found to be necessary.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company	Sities Service Oll Company		
Address	Tos 97		2.
	Bobha, So. Centeo	Ву	Jtty
		Title	isst. iv. apt.
		F 16-8437-5	

$(1+2) \ge H^{1/2} + \frac{1}{2} + \frac{1}{2$

and and the second state of the