Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

I the Commission.	Indicate nature of re	port by checking below:	,	
EPORT ON BEGINNING DRILLING	OPERATIONS	REPORT ON REPA	TRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING		
EPORT ON RESULT OF TEST OF SHUT-OFF	CASING	REPORT ON DEEL	PENING WELL	
EPORT ON RESULT OF PLUGGING	OF WELL		2 L - 2 l - 2	<u> </u>
Hobbs, No				
OIL CONSERVATION COMMISSION CONTROL For New Mexico. Sentlemen: Following is a report on the work		Place tained under the headin	g noted above at the	
Following is a report on the work [ide Water Associated	Oil Company.	• · A · Day	Well No	in the
Company or Operator		. T. Lease 22	R	N. M. P. M.,
South Eunies	Field,	Lea		County.
The dates of this work were as followed	ows:	6/28/37	6/28/37	
Notice of intention to do the work	was [subm	itted on Form 0-102 on		
perforation below, a gas, it was then trein and it flowed 22-through open 2-3/8" Witnessed by Loyd Lamb	DUPLIC	M / G B C Z 1	JUN 30 CO	Title
	ame		firm that the information	on given above
Subscribed and sworn to before	me this	is true and correct.		
an Turne	37	Name	muick-	· · · · · · · · · · · · · · · · · · ·
29day of	, 13	Position Prod	Sup't.	
alrem 1	Notary Public	Representing Tide	Water Associa	ted 011 0
My Commission expires Octo	er 24, 1939		Company or Opera	
Remarks:			July &	fiera Mame Inspector
			lita:	Title
			JUN 30	1937