

CLAYTON W. WILLIAMS, JR., INC.

3000 CLAYDESTA NATIONAL BANK BUILDING
SIX DESTA DRIVE
MIDLAND, TEXAS 79705
915/682-6324

STATE OF NEW MEXICO
Oil Conservation Division
P. O. Box 1980
Hobbs, New Mexico 88241

January 30, 1992

Attn: Mr. Jerry Sexton

RE: State A A/C 2 #49, C 8-22-36
Delinquent Packer Leakage Test

Mr. Sexton;

The above referenced well is not a Eunice-SR-Queen South completion, nor does it have a packer in the hole. A diagram of the current well bore is enclosed. The well was converted from a dual South Eunice/Jalmat to a single Jalmat completion with a 1" velocity string in December of 1972.

The well is currently TA'd in the Jalmat gas pool and is carried as such on the C-115 reports.

Please call me at 915/688-3239 if you have any questions or if I can provide further information to clear up this matter.

Thanks,



David Grafe
Petr. Engineer

Enclosures
DGG/rsm

*Back on this letter +
attachments.
Revised 3/1/92 Eunice SR-Queen, SR
1.15 7.31.92*