

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-08842 ✓
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name State A AC 2
2. Name of Operator Clayton W. Williams, Jr., Inc.	8. Well No. 55
3. Address of Operator Six Desta Drive, Suite 3000 Midland, Texas 79705	9. Pool name or Wildcat Eunice 7 Rvrs Queen South
4. Well Location Unit Letter P : 660 Feet From The South Line and 660 Feet From The East Line Section 8 Township 22S Range 36E NMPM Lea County	10. Elevation (Show whether DP, RKB, RT, GR, etc.) GL - 3581'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12/07/90 CIBP set @ 3710'/

3/15/93 Spot 30 sx Class "C" w/2% CaCl2 on CIBP. Displaced hole w/100 bbls 10 PPG gelled brine. POOH to 2600'. Spot 30 sx cement plug 2600-±2311'. POOH to 610'. Spot 30 sx cement plug 610 - ±330'. Perforate 5-1/2" casing @ 330', 2 SPF. Pump 95 sx Class "C" w/2% CaCl2 down 5-1/2" casing and up 5-1/2"/8-5/8" annulus. Circulate 5 sx cement to pits. Cut casing off 3' below G.L. and install P & A marker.

SEE ATTACHED WELLBORE DIAGRAM

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Grafe TITLE Petroleum Engineer DATE 3/26/93
TYPE OR PRINT NAME David Grafe TELEPHONE NO. 682-6324

(This space for State Use)

APPROVED BY Charles L. Lessor TITLE OIL & GAS INSPECTOR DATE APR 20 1993
CONDITIONS OF APPROVAL, IF ANY: