

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-08846

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

State A AC 2

8. Well No.

50

9. Pool name or Wildcat

Eunice 7 Rvrs Queen South

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Clayton Williams Energy, Inc.

3. Address of Operator

Six Desta Drive, Suite 3000 Midland, Texas 79705

4. Well Location

Unit Letter A : 660 Feet From The North Line and 660 Feet From The East Line

Section

9

Township

22S

Range

36E

NMPM

Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work will commence upon OCD approval

1) CIBP @ 3640' w/35' cement on CIBP (3/31/94)

2) Circulate hole w/10 ppg gelled brine from CIBP to surface.

3) Perforate 5-1/2" casing @ ±320'.

4) Circulate cement down the 5-1/2" csg and up the 5-1/2"/8-5/8" annulus.
(80 sx Class C w/5% CaCl₂)

5) Cut the 5-1/2" and 8-5/8" csg 3' below GL. Set P & A marker. Cut Deadmen.
Clear location of all junk. *Plug and Abandon Wellbore*

*See attached wellbore diagram)

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
PLUG AND ABANDON OPERATIONS FOR THE C-103
TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

David G. Grafe

TITLE Senior Prod. Engineer

DATE 06/09/94

TYPE OR PRINT NAME

David G. Grafe

TELEPHONE NO. 682-6324

(This space for State Use)

ORIGINAL CERTIFICATE OF APPROVAL
DISTRICT I APPROVAL

JUN 13 1994

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUN 1 2006

U.S. DEPARTMENT OF
ENERGY