

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Dec 13 3 40 PM '65

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Gulf Oil Corporation	8. Firm or Lease Name H. T. Mattern (NCT-E)
3. Address of Operator Box 670, Hobbs, New Mexico	9. Well No. 8
4. Location of Well UNIT CENTER H 2310 FEET FROM THE North LINE AND 990 FEET FROM THE East LINE, SECTION 12 TOWNSHIP 22-S RANGE 36-E N.M.P.M.	10. Field and Pool, or Wildcat Arrowhead
15. Elevation (Show whether L.F., R.F., G.R., etc.) 3452 GL	16. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>
BUILD UP AFTER CASING	<input type="checkbox"/>
OTHER	<input type="checkbox"/>
PLUG AND ABANDON	<input type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK	<input type="checkbox"/>
COMMENCE DRILLING OPER.	<input type="checkbox"/>
CASING TO AND CEMENT JOBS	<input type="checkbox"/>
OTHER	<input type="checkbox"/>
ALTERING CASING	<input type="checkbox"/>
PLUG AND ABANDONMENT	<input type="checkbox"/>

Plugged and abandoned.

17. Location, Progress or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3750' TD, 3736' PB.

Pulled tubing, rods and pump. Ran steel line measurement to 3523'. Plugged back from 3523' to 3486' with pea gravel. Ran tubing open ended and tagged gravel at 3486'. Loaded hole with mud. Spotted 80' cement plug (10 sacks) on top of gravel. Spotted 200' cement plug (25 sacks) from 550' to 350'. Spotted 10 sack plug from 80' to surface. Installed dry hole marker and cleaned location. (Location is ready for inspection) Complete December 13, 1965.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED _____ TITLE **Area Production Manager** DATE **December 13, 1965**

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: