

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-08885
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-1506
7. Lease Name or Unit Agreement Name	State 157 "D"
8. Well No.	4
9. Pool name or Wildcat	Eumont Queen Gas
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3456 GR

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator ARCO OIL AND GAS COMPANY
3. Address of Operator P. O. Box 1610, Midland, Texas 79702	4. Well Location Unit Letter I : 2310 Feet From The South Line and 990 Feet From The East Line
5. Section 12 Township 22S Range 36E NMPM Lea County	6. Section 12 Township 22S Range 36E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-23-90. RUPU. POH W/CA. CO to 3500. Perf Eumont f/2652-3186 (selected 30 holes). A<sup>size</sup>perfs 2652-3495 w/5000 gals. Swab load. Set RBP at 3242. A Eumont perfs 2652-3186 w/2000 gals. Frac w/24,500 gals & 32,000# sd. Raise RBP to 2635. Cmt'd holes in csg at 1150 w/440 sx "C". Circ to surf. WOC. DO CMT. Press test csg to 500#. POH w/RBP. Ran CA: 2 3/8 tby & pkr to 3241. Set pkr at 2540.

5-08-90. RDPU.

5-12-90. In 24 hrs flwd 0 BO, 0 BW, 316 MCF, FTP 50#. Full open ck.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ken W. Gosnell TITLE Engr. Tech. DATE 5/16/90

TYPE OR PRINT NAME Ken W. Gosnell 915/688-5672 TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

MAY 22 1990