

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
157	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Atlantic Richfield Company		8. Farm or Lease Name State 157 "D"
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240		9. Well No. 5
4. Location of Well UNIT LETTER <u>P</u> <u>330</u> FEET FROM THE <u>South</u> LINE AND <u>330</u> FEET FROM THE <u>East</u> LINE, SECTION <u>12</u> TOWNSHIP <u>22S</u> RANGE <u>36E</u> NMPM.		10. Field and Pool, or Wildcat Arrowhead Grayburg
15. Elevation (Show whether DF, RT, GR, etc.) 3480' GR		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On 11/18/75 rigged up, installed BOP. WIH w/CIBP on WL, set BP @ 3500'. WIH w/tbg OE, tagged BP @ 3500'. Spotted 20 sx Cl C cmt on top of BP. Top of plug @ 3343'. POH w/tbg. Free point indicated @ 735'. Shot 7" csg @ 735'. Pld & rec 735' of 7" OD csg. Filled hole w/heavy gelled mud between all cement plugs. Spotted 45 sx Cl C cmt cont'g 4% gel, 2% CaCl across 7" OD csg stub @ 735'. Spotted 45 sx Cl C cmt cont'g 4% gel & 2% CaCl across 9-5/8" OD csg shoe @ 322'. Spotted 10 sx cmt plug @ surface. Installed regulation dry hole marker. Cleaned & leveled location. Well P&A eff 11/19/75.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>La Roy Frost</u>	TITLE <u>Dist. Drlg. Supv.</u>	DATE <u>11/24/75</u>
APPROVED BY <u>John W. Runyan</u>	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		